




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE10360</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	8779909151																								
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	23-12-2023 12:21:48																						
<b>Vendor Details :</b>																									
Company Name/Client Name :	Tivon Park E/F/G/H Wing	Customer's Mobile :	8779909151	Name :	Bhavesh Sir																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
<b>Product Name :</b>	CCTV																								
<b>Complain :</b>	1)F wing backside main gate cable need to check																								
<b>Technician Comment :</b>	Camera nmbr 3 was hanging so fixed it proper and all 16 cameras recording was on so off all recording only 4 cameras recording on and main construction gate side one camera cable faulty from joint to camera end so it's painding.																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	Camera nmbr 3 was hanging so fixed it proper and all 16 cameras recording was on so off all recording only 4 cameras recording on and main construction gate side one camera cable faulty from joint to camera end so it's painding.																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>26-12-2023 03:56:44</td><td>Atique Salmani</td><td>Completed</td><td></td><td>-</td></tr><tr><td>25-12-2023 05:04:29</td><td>Atique Salmani</td><td>Work Pending</td><td>Camera nmbr 3 was hanging so fixed it proper and all 16 cameras recording was on so off all recording only 4 cameras recording on and main construction gate side one camera cable faulty from joint to camera end so it's painding.</td><td></td></tr><tr><td>25-12-2023 10:02:08</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	26-12-2023 03:56:44	Atique Salmani	Completed		-	25-12-2023 05:04:29	Atique Salmani	Work Pending	Camera nmbr 3 was hanging so fixed it proper and all 16 cameras recording was on so off all recording only 4 cameras recording on and main construction gate side one camera cable faulty from joint to camera end so it's painding.		25-12-2023 10:02:08	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
26-12-2023 03:56:44	Atique Salmani	Completed		-																					
25-12-2023 05:04:29	Atique Salmani	Work Pending	Camera nmbr 3 was hanging so fixed it proper and all 16 cameras recording was on so off all recording only 4 cameras recording on and main construction gate side one camera cable faulty from joint to camera end so it's painding.																						
25-12-2023 10:02:08	Atique Salmani	New		-																					

Previous Complain History :			
	<b>Date Time</b>	<b>Technician Name</b>	<b>Remark</b>
	14-12-2023 10:36:10	PravinJagade	G wing 1 canera recordings off issue resolve working done and 1 camera view delete issue resolve. H wing office dvr 2 camera no video issue resolve and 1 camera falty and cable need to check. 3 dc use and 2 BNC use.
	23-11-2023 01:15:51	InzmamUl Haq	Tivon park F- WING Total camera 9 DVR Connect Working camera 6 2 camera lift OFF 1 lift BNC problem 2 lift power problem 3 car parking backside Playback 47 days 7/12/23 G-WING Total camera DVR Connect 10 Working camera 9 1 camera black side problem Playback 117days 7/12/23 H-WING Total camera DVR Connect 8 Working camera 8 All cera working done 10 pic BNC 5 PIC DC 4camera back side camera not working all cable check karne parega