

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE2046																														
Priority :	High																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	8286153419																													
Technician Name :	Yasin Shaikh		Technician Mobile :	8689802313																										
Ticket Type :	Complain	Date & Time :	19-10-2020 10:56:59																											
Vendor Details :																														
Company Name/Client Name :	Royal Dryfruits	Customer's Mobile :	8286153419	Name :	Dipesh Sir																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
Product Name :	CCTV																													
Complain :	cabling																													
Technician Comment :	3 new camera cabling 15 metre armoured cable cat6																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	3 new camera cabling 15 metre armoured cable cat6																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>20-10-2020 06:24:02</td><td>YasinShaikh</td><td>Completed</td><td>3 new camera cabling 15 metre armoured cable cat6</td><td></td></tr><tr><td>20-10-2020 01:56:35</td><td>YasinShaikh</td><td>New</td><td></td><td>-</td></tr><tr><td>19-10-2020 10:57:25</td><td>YasinShaikh</td><td>New</td><td></td><td>-</td></tr><tr><td>19-10-2020 10:56:59</td><td>YasinShaikh</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	20-10-2020 06:24:02	YasinShaikh	Completed	3 new camera cabling 15 metre armoured cable cat6		20-10-2020 01:56:35	YasinShaikh	New		-	19-10-2020 10:57:25	YasinShaikh	New		-	19-10-2020 10:56:59	YasinShaikh	New		-
Date Time	Technician Name	Status	Remark	Sign																										
20-10-2020 06:24:02	YasinShaikh	Completed	3 new camera cabling 15 metre armoured cable cat6																											
20-10-2020 01:56:35	YasinShaikh	New		-																										
19-10-2020 10:57:25	YasinShaikh	New		-																										
19-10-2020 10:56:59	YasinShaikh	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>05-10-2020 04:54:33</td><td>Atique Salmani</td><td>find out the cut cable and rejoint 5cameras working ok date time also ok</td></tr><tr><td>21-07-2020 12:37:55</td><td>Atique Salmani</td><td>setvey done one Bullet camera 50 mtr and one dome camera cabling rj6n 2 core approxmatly 150 to 160 mtr. and cameras vedeo loss DP 2 and 5th floor issue resolved all cameras working ok only one middle lift v loss due to cable inside the lift duct last visit ihave told.</td></tr></tbody></table>					Date Time	Technician Name	Remark	05-10-2020 04:54:33	Atique Salmani	find out the cut cable and rejoint 5cameras working ok date time also ok	21-07-2020 12:37:55	Atique Salmani	setvey done one Bullet camera 50 mtr and one dome camera cabling rj6n 2 core approxmatly 150 to 160 mtr. and cameras vedeo loss DP 2 and 5th floor issue resolved all cameras working ok only one middle lift v loss due to cable inside the lift duct last visit ihave told.																
Date Time	Technician Name	Remark																												
05-10-2020 04:54:33	Atique Salmani	find out the cut cable and rejoint 5cameras working ok date time also ok																												
21-07-2020 12:37:55	Atique Salmani	setvey done one Bullet camera 50 mtr and one dome camera cabling rj6n 2 core approxmatly 150 to 160 mtr. and cameras vedeo loss DP 2 and 5th floor issue resolved all cameras working ok only one middle lift v loss due to cable inside the lift duct last visit ihave told.																												