## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

Service Status Det	ails: VE4817								
Priority: Low									
Created By :	Admin - Apurva Vajaria								
Complaint Mob.	8451099978								
Technician Name :	Ravi Rajbhar				Technician Mobile: 8080922965				
Ticket Type :	Complain	Da	te & Time :	19-02-2022 10:18:22					
Vendor Details :									
Company Name/Client Name :	Dev Research Cus Centre :		stomer's Mobile	)	8451099978		Name :	Hitesh Doshi	
Address:									
Mumbai,,,,Mah	arashtra								
AMC Details :									
Expiry Date :	06-06-2021 12:00:00				Type: Comprehen		Comprehensi	ve	
<b>Product Name:</b>	Access								
Complain:	Repaired f12 need to install								
Technician Comment :	essl access control terminal device repair return with install all ok working done and security cabin fire panel 2 zone check all ok working done								
Complain Operator :	Desktop - Apurva Vajaria								
Remark:	essl access control terminal device repair return with install all ok working done and security cabin fire panel 2 zone check all ok working done								
<b>Status History:</b>	Date Time		Technician Name		Status	Remark		Sign	
	19-02-2022 12:24:16		Ravi Rajbhar		Completed	essl access control terminal device repair return with install all ok working done and security cabin fire panel 2 zone check all ok working done		9 22	
	19-02-2022 10:18:37		Ravi Rajbhar		New			-	
	19-02-2022 10:18:22		Ravi Rajbhar		New			-	
Previous Complain	Light Time Lechnician N				Remark				
History :	19-02-2022 12:32:29	Ravi Rajbhar		fire panel hooter replace and ok working done main gate and biometric attendance issue all data clear old new 17 porson add in divice and data download ok working software					
	04-02-2022 10:29:01	Siddhesh Chavan		PPM work of Acess , Fire, Epbax done All smoke detector cleaned . and also all door acces checked MCP , hooter fire test done. intercom system working ok all line working ok. 2) 1 st floor biomatric machines take to office for checking and finger sensor not working					