Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Details: VE15903							
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	8879250068						
Technician Name :	Atique Salmani		Technic	echnician Mobile 808092298			
Ticket Type :	Complain	Date & Time :	29-09-20	29-09-2025 12:01:41			
Vendor Details :			-				
Company Name/Client Name :	HEMANT SIR	Customer's Mobile :	8879250	0068	Name :	Jaswanti Jewel Rehab	
Address:			-		-		
Mumbai , , , , Mal	narashtra						
AMC Details:							
Expiry Date :	01-01-1970 05:30:	Type:	Type :				
Product Name:	CCTV						
Complain:	soceity ofc and lobby panel cctv need to check						
Technician Comment :	2 camera painding 1 lift no one can open lift for chek camera 2nd lobby entry gate bullet camera height ladder not available so it's painding						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	2 camera painding 1 lift no one can open lift for chek camera 2nd lobby entry gate bullet camera height ladder not available so it's painding						
Status History:	Date Time	Technician Name	Status]	Remark	Sign	
	29-09-2025 12:04:04	Atique Salmani	Completed	can open lift lobby entry g	nding 1 lift no one for chek camera 21 ate bullet camera r not available so it		
	29-09-2025 12:04:04	Atique Salmani	Completed	can open lift lobby entry g	nding 1 lift no one for chek camera 21 ate bullet camera not available so it		
	29-09-2025 12:01:49	Atique Salmani	New			-	

Previous Complain History :	Date Time	Technician Name	Remark	
	19-11-2025 10:43:38	Atique Salmani	In Hikvision nvr recording on working ok and in unv nvr event recording on from camera login end all working ok.	
	15-11-2025 11:38:07	Atique Salmani	22nd to ground agel starting done and naming also done according to amit sir 21 floor view chek working ok entry camera resetting angel painding due to ladder and event motion recording painding .	