

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE6591																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9819121121																								
Technician Name :	Chandan Yadav		Technician Mobile :	9833262842																					
Ticket Type :	Complain	Date & Time :	14-10-2022 01:03:05																						
Vendor Details :																									
Company Name/Client Name :	Vajaria Enterprises	Customer's Mobile :	9819121121	Name :	Keval Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	CCTV																								
Complain :	Site : Arika godown goregaon east - cctv system dismental																								
Technician Comment :	cctv system dismental 11 dome camera 3 bullate camera 12.4*4 box 4 power supply 16 channel Hikvision dvr 4u ruck 28 video bullon 14 dc pin 4 TB HDD 1 spaygard work completed.																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	cctv system dismental 11 dome camera 3 bullate camera 12.4*4 box 4 power supply 16 channel Hikvision dvr 4u ruck 28 video bullon 14 dc pin 4 TB HDD 1 spaygard work completed.																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>14-10-2022 02:16:30</td><td>ChandanYadav</td><td>Completed</td><td>cctv system dismental 11 dome camera 3 bullate camera 12.4*4 box 4 power supply 16 channel Hikvision dvr 4u ruck 28 video bullon 14 dc pin 4 TB HDD 1 spaygard work completed.</td><td></td></tr><tr><td>14-10-2022 01:03:20</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>14-10-2022 01:03:05</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	14-10-2022 02:16:30	ChandanYadav	Completed	cctv system dismental 11 dome camera 3 bullate camera 12.4*4 box 4 power supply 16 channel Hikvision dvr 4u ruck 28 video bullon 14 dc pin 4 TB HDD 1 spaygard work completed.		14-10-2022 01:03:20	ChandanYadav	New		-	14-10-2022 01:03:05	ChandanYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																					
14-10-2022 02:16:30	ChandanYadav	Completed	cctv system dismental 11 dome camera 3 bullate camera 12.4*4 box 4 power supply 16 channel Hikvision dvr 4u ruck 28 video bullon 14 dc pin 4 TB HDD 1 spaygard work completed.																						
14-10-2022 01:03:20	ChandanYadav	New		-																					
14-10-2022 01:03:05	ChandanYadav	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>12-10-2022 01:30:48</td><td>ChandanYadav</td><td>ac duck water server room and server room Power fluctuated.one power supply burn change the power supply and cctv working ok. power supply barcode.39227</td></tr><tr><td>08-10-2022 04:05:35</td><td>ChandanYadav</td><td>4 camera not working 3 camera cakble folti 1 working ok cakble folti 3rd floor &4rd floor and basment. All camera nameging . cctv work completed. three camera cakble ieesu .</td></tr></tbody></table>					Date Time	Technician Name	Remark	12-10-2022 01:30:48	ChandanYadav	ac duck water server room and server room Power fluctuated.one power supply burn change the power supply and cctv working ok. power supply barcode.39227	08-10-2022 04:05:35	ChandanYadav	4 camera not working 3 camera cakble folti 1 working ok cakble folti 3rd floor &4rd floor and basment. All camera nameging . cctv work completed. three camera cakble ieesu .											
Date Time	Technician Name	Remark																							
12-10-2022 01:30:48	ChandanYadav	ac duck water server room and server room Power fluctuated.one power supply burn change the power supply and cctv working ok. power supply barcode.39227																							
08-10-2022 04:05:35	ChandanYadav	4 camera not working 3 camera cakble folti 1 working ok cakble folti 3rd floor &4rd floor and basment. All camera nameging . cctv work completed. three camera cakble ieesu .																							