Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Details : VE8385										
Priority:	Low									
Created By:	Admin - Apurva Vajaria									
Complaint Mob. No. :	7738060558									
Technician Name :	Yogesh Desai		Technician Mobile :	8080922963						
Ticket Type :	Complain	Date & Time :	20-05-2023 11:21:08							
Vendor Details	Vendor Details :									
Company Name/Client Name :	Vinayak Developers (Mahavir Spring)	Customer's Mobile :	7738060558	Name :	Malesh Sir					
Address:										
Mumbai,,,,	Maharashtra									
AMC Details :										
Expiry Date :	01-01-1970 05:30:00		Type:							
Product Name :	CCTV									
Complain:	2 cameras not working and 3-4 cameras angle need to set									
Technician Comment :	Two camera angle setting done One camera on gate no 3 camera reconnected camera working ok One camera inside near gate no 3 one camera was disconnected cable was lying on ground we reconnected and camera is working ok. Camera view showing black and white need to change lense need to be cleaned. Gate no 2 camera cable break from two sides need to change cable and one new bullet camera also required.camera cable about 300 to 400 mtrs approx. Ptz camera need to be shifted from sale office to side building approx cable 150 to 200 mtrs approx									
Complain Operator :	Desktop - Apurva Vajaria									
Remark :	Two camera angle setting done One camera on gate no 3 camera reconnected camera working ok One camera inside near gate no 3 one camera was disconnected cable was lying on ground we reconnected and camera is working ok. Camera view showing black and white need to change lense need to be cleaned. Gate no 2 camera cable break from two sides need to change cable and one new bullet camera also required.camera cable about 300 to 400 mtrs approx. Ptz camera need to be shifted from sale office to side building approx cable 150 to 200 mtrs approx									

Status History :	Date Time	Time Technician Name		Sta	tus	Remark	Sign	
	20-05-2023 05:23:40	Yoge	eshDesai	Comp	leted	Two camera angle setting done One camera on gate no 3 camera reconnected camera working ok One camera inside near gate no 3 one camera was disconnected cable was lying on ground we reconnected and camera is working ok. Camera view showing black and white need to change lense need to be cleaned. Gate no 2 camera cable break from two sides need to change cable and one new bullet camera also required.camera cable about 300 to 400 mtrs approx. Ptz camera need to be shifted from sale office to side building approx cable 150 to 200 mtrs approx	PMS	
	20-05-2023 11:21:19	Yoge	eshDesai	New			-	
Previous Complain	Date Time Tec		Technician Name			Remark		
History:	02-05-2023 11:52:40		PravinJagade		1 camera not working resolve working done 2 camera angle setting done. 1 camera new BNC change.			
	20-10-2022 10:4	9:27	Munna Gupta		ptz camera shifting and preset setting. ptz camere ka glass damage ho chuka hai jiski wajah se picture clear nahin a raha hai.			