







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE4663																																			
Priority :	Low																																		
Created By :	Admin - Apurva Vajaria																																		
Complaint Mob. No. :	9022904145																																		
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																															
Ticket Type :	Complain	Date & Time :	28-01-2022 11:29:06																																
Vendor Details :																																			
Company Name/Client Name :	VIP PLAZA CO OPERATIVE PREMISES SOCIETY LTD	Customer's Mobile :	9022904145	Name :	Raghu Sir																														
Address :																																			
Mumbai , , , , Maharashtra																																			
AMC Details :																																			
Expiry Date :	12-01-2021 12:00:00		Type :	Comprehensive																															
Product Name :	Intercom																																		
Complain :	intercom system need to check																																		
Technician Comment :	B wing duct side cable check but office side cable & phone not found b wing busment cron weak (crystal 48 line old version system password missing)																																		
Complain Operator :	Desktop - Apurva Vajaria																																		
Remark :	B wing duct side cable check but office side cable & phone not found b wing busment cron weak (crystal 48 line old version system password missing)																																		
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>31-01-2022 04:48:08</td><td>Ravi Rajbhar</td><td>Completed</td><td>B wing duct side cable check but office side cable & phone not found b wing busment cron weak (crystal 48 line old version system password missing)</td><td></td></tr><tr><td>31-01-2022 12:57:16</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>28-01-2022 06:23:05</td><td>Ravi Rajbhar</td><td>Work Pending</td><td>a wing office line check all line working in duck and also office to duck cable issue and ground floor duck all intercom line ok</td><td></td></tr><tr><td>28-01-2022 11:29:19</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>28-01-2022 11:29:06</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	31-01-2022 04:48:08	Ravi Rajbhar	Completed	B wing duct side cable check but office side cable & phone not found b wing busment cron weak (crystal 48 line old version system password missing)		31-01-2022 12:57:16	Ravi Rajbhar	New		-	28-01-2022 06:23:05	Ravi Rajbhar	Work Pending	a wing office line check all line working in duck and also office to duck cable issue and ground floor duck all intercom line ok		28-01-2022 11:29:19	Ravi Rajbhar	New		-	28-01-2022 11:29:06	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																															
31-01-2022 04:48:08	Ravi Rajbhar	Completed	B wing duct side cable check but office side cable & phone not found b wing busment cron weak (crystal 48 line old version system password missing)																																
31-01-2022 12:57:16	Ravi Rajbhar	New		-																															
28-01-2022 06:23:05	Ravi Rajbhar	Work Pending	a wing office line check all line working in duck and also office to duck cable issue and ground floor duck all intercom line ok																																
28-01-2022 11:29:19	Ravi Rajbhar	New		-																															
28-01-2022 11:29:06	Ravi Rajbhar	New		-																															

Previous Complain History :			
	Date Time	Technician Name	Remark
	15-02-2022 11:37:04	Ravi Rajbhar	
	11-02-2022 02:54:37	Atique Salmani	terrace camera issue resolved by reconnection and working ok b302 b 204 2 camera need to changed one is pinkish and is more disturbance .