Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Det	ails : VE9086						
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	9892982500						
Technician Name :	Atique Salmani		Technic:	echnician Mobile 80		8080922984	
Ticket Type :	Complain	Date & Time :	07-08-2023 03:48:50		-		
Vendor Details :							
Company Name/Client Name :	Lifescapes Mirage	Customer's Mobile :	9892982500		Name :	Rakesh Sanghavi	
Address:							
Mumbai , , , 4000	28 , Maharashtra						
AMC Details :							
Expiry Date :	01-01-1970 05:30:0	0	Type:				
Product Name:	CCTV						
Complain:	1)1 lift camera not working and 2-3 cameras not working 2)4 lift intercom need to shift little downside						
Technician Comment :	One lift camera vedeo cable faulty power ok 13:floor camera vedeo loss issue resolved by changed BNC dc becz totally rushted working ok set angel working ok and 4 all lift intercom shifted .						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	One lift camera vedeo cable faulty power ok 13:floor camera vedeo loss issue resolved by changed BNC dc becz totally rushted working ok set angel working ok and 4 all lift intercom shifted .						
Status History :	Date Time	Technician Name	Status	1	Remark	Sign	
	07-08-2023 05:48:30	Atique Salmani	Completed	One lift camera vedeo cable faulty power ok 13:floor camera vedeo loss issue resolved by changed BNC dc becz totally rushted working ok set angel working ok and 4 all lift intercom shifted .			
	07-08-2023 03:49:04	Atique Salmani	New			-	
Previous Complain History :	Date Time	Technician Name	Remark				
	22-08-2023 12:49:21	DilshadKhan	Dvr off issu Resolved and solve and recording so				
	10-08-2023 11:39:52	Atique Salmani	Back side wing if need to cover all flate door thenn to Add new cameras all floor $1805/6$ cable duct to flate not available long time and 1103 connection done from instrument side and also duct side .				