


Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE8533					
Priority :	Low				
Created By :	Admin - Apurva Vajaria				
Complaint Mob. No. :	7021671156				
Technician Name :	Munna Gupta		Technician Mobile :	8080922982	
Ticket Type :	AMC visiting	Date & Time :	09-06-2023 11:41:20		
Vendor Details :					
Company Name/Client Name :	Lokhandwala Foundation	Customer's Mobile :	7021671156	Name :	Rauf Sir
Address :					
Mumbai , , , , Maharashtra					
AMC Details :					
Expiry Date :	01-01-1970 05:30:00		Type :		
Product Name :	Ppm				
Complain :	PA speaker some noise issue Principle Madam cabin epabx line not working and CCTV/PA/EPABX/Intercom PPM need to do				
Technician Comment :	PA bell me se haming sound aa raha tha. Bell ke ander speaker disconnect Kiya jiske wajah se ye problem solve ho Gaya . intercom complan 1102/1104 complete.ppm incomplete.system working properly.				
Complain Operator :	Desktop - Apurva Vajaria				
Remark :	PA bell me se haming sound aa raha tha. Bell ke ander speaker disconnect Kiya jiske wajah se ye problem solve ho Gaya . intercom complan 1102/1104 complete.ppm incomplete.system working properly.				
Status History :	Date Time	Technician Name	Status	Remark	Sign
	09-06-2023 01:30:15	Munna Gupta	Completed	PA bell me se haming sound aa raha tha. Bell ke ander speaker disconnect Kiya jiske wajah se ye problem solve ho Gaya . intercom complan 1102/1104 complete.ppm incomplete.system working properly.	
	09-06-2023 11:41:28	Munna Gupta	New		-
Previous Complain History :	Date Time	Technician Name	Remark		
	04-05-2023 11:24:32	ChandanYadav	Intercom connection solve.		
	28-04-2023 05:03:43	Kalpesh SubhashGurav	Free Counter Direct Line Disconnect and Swap Direct Line in MD Cabin Principal cabin intercom connection shift Director cabin ok. Principal PA Intercom Connection found the wire and turned on the line. The reception cable is not installed		