Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | **W** : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE7937					
Priority :	Low				
Created By :	Admin - Apurva Vajaria				
Complaint Mob. No. :	28170556				
Technician Name :	Ravi Rajbhar		**Technician Mobile :**	8080922965	
Ticket Type :	Complain	**Date & Time :**	23-03-2023 11:38:08		
Vendor Details :					
Company Name/Client Name :	Rahul Group Of Schools & College - HO	Customer's Mobile :	28170556	Name :	Shivani Madam
Address :					
Mumbai , , , , Maharashtra					
AMC Details :					
Expiry Date :	01-01-1970 05:30:00		Type :		
Product Name :	Intercom				
Complain :	Intercom shifting work				
Technician Comment :	rahul ho office skylink epbax system shifting done and 5 new crown modul uesd and all ex. no. ok working done and 3 CO line connecte in system and in side 3 ex. no. pending client side bcz cable not drop to switch board total 20 line ok working done				
Complain Operator :	Desktop - Apurva Vajaria				
Remark :	rahul ho office skylink epbax system shifting done and 5 new crown modul uesd and all ex. no. ok working done and 3 CO line connecte in system and in side 3 ex. no. pending client side bcz cable not drop to switch board total 20 line ok working done				

Status History :

Date Time	Technician Name	Status	Remark	Sign
24-03-2023 05:56:06	Ravi Rajbhar	Completed	rahul ho office skylink epbax system shifting done and 5 new crown modul uesd and all ex. no. ok working done and 3 CO line connecte in system and in side 3 ex. no. pending client side bcz cable not drop to switch board total 20 line ok working done	
24-03-2023 10:01:30	Ravi Rajbhar	New		-
23-03-2023 11:38:24	Ravi Rajbhar	New		-

Previous Complain History :

Date Time	Technician Name	Remark
18-04-2023 10:32:57	SantoshPathak	Kalpesh visited - Extension number 25 issue checked working properly
04-04-2023 10:05:08	Ravi Rajbhar	38, 36 , ex. no. punching in cron with cable check 1st floor staff room all ok working done and ex. no switch 24