


Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | **W :** www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE10294					
Priority :	Low				
Created By :	Admin - Apurva Vajaria				
Complaint Mob. No. :	9833444560				
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965	
Ticket Type :	AMC visiting	Date & Time :	16-12-2023 11:45:51		
Vendor Details :					
Company Name/Client Name :	Comfort Inn Emerald Dapoli	Customer's Mobile :	9833444560	Name :	Abhay Mutreja
Address :					
Mumbai , , , , Maharashtra					
AMC Details :					
Expiry Date :	01-01-1970 05:30:00		Type :		
Product Name :	Ppm				
Complain :	CCTV / EPABX /PA /Access/ Fire				
Technician Comment :	ppm done of cctv camera , fire ,access, PA system 1- cctv camera all ok working done check our side one camera trecce on off issue resolved 2 - fire panal all zone normal with mcp check all floor all ok working 3- PA system check one amplifier ok working resturanrt and recepatiin area second amplifier floor already remove 4- epbax complaints 108,209, both lift ,party area ,1sfloor and second floor 1st floor cable breck need to change cable 35-40 meter and service lift cable breck need to change cable lift room to lift in side 108 cable missing in room both side and need to cabling system to room 209 jack issue need to change 5- access already ok ok working and check our side				
Complain Operator :	Desktop - Apurva Vajaria				
Remark :	ppm done of cctv camera , fire ,access, PA system 1- cctv camera all ok working done check our side one camera trecce on off issue resolved 2 - fire panal all zone normal with mcp check all floor all ok working 3- PA system check one amplifier ok working resturanrt and recepatiin area second amplifier floor already remove 4- epbax complaints 108,209, both lift ,party area ,1sfloor and second floor 1st floor cable breck need to change cable 35-40 meter and service lift cable breck need to change cable lift room to lift in side 108 cable missing in room both side and need to cabling system to room 209 jack issue need to change 5- access already ok ok working and check our side				

Status History :					
	Date Time	Technician Name	Status	Remark	Sign
	16-12-2023 07:37:56	Ravi Rajbhar	Completed	ppm done of cctv camera , fire ,access, PA system 1- cctv camera all ok working done check our side one camera trecce on off issue resolved 2 - fire panal all zone normal with mcp check all floor all ok working 3- PA system check one amplifier ok working resturanrt and recepatiin area second amplifier floor already remove 4- epbax complaints 108,209, both lift ,party area ,1sfloor and second floor 1st floor cable breck need to change cable 35-40 meter and service lift cable breck need to change cable lift room to lift in side 108 cable missing in room both side and need to cabling system to room 209 jack issue need to change 5-access already ok ok working and check our side	
	16-12-2023 11:46:16	Ravi Rajbhar	New		-
Previous Complain History :					
	Date Time	Technician Name	Remark		
	16-12-2023 11:44:15	Ravi Rajbhar	room number 305 essl access lock install with configuration done one card and 3 key hondover to Dilip sir		
	27-11-2023 01:36:55	Sonu Kumar	2tb hard disk install all working ok and 1camera off issue resolved working ok		