




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE6826																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9833444560																			
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																
Ticket Type :	AMC visiting	Date & Time :	13-11-2022 11:43:08																	
Vendor Details :																				
Company Name/Client Name :	Comfort Inn Emerald	Customer's Mobile :	9833444560	Name :	Abhay Mutreja															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	Ppm																			
Complain :	Cctv/Access/Epabx/PA/Fire																			
Technician Comment :	ppm done.																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	ppm done.																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>13-11-2022 04:29:40</td><td>Atique Salmani</td><td>Completed</td><td>ppm done.</td><td></td></tr><tr><td>13-11-2022 11:43:17</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	13-11-2022 04:29:40	Atique Salmani	Completed	ppm done.		13-11-2022 11:43:17	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																
13-11-2022 04:29:40	Atique Salmani	Completed	ppm done.																	
13-11-2022 11:43:17	Atique Salmani	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>22-10-2022 11:03:07</td><td>Atique Salmani</td><td>Ground floor main entry Smoke Detector cahnged Based changed on third floor /304/306/308/302 Allzones working on healthy condition. 1.Intercom .309 line was dead repunching and instruments end also reconnection from 2 ends switch board to next swich board . 2.306 checked line reconnection form rj 11 and working ok 3.308 instrument to rj 11 female socket cable faulty changed also cable instrument to rj11 changed working ok. 4.108 1st floor staircase to room nmbr 108 cable faulty line ok . Cable need to changed south gate camera new installed but mode didn't changed so again installed old camera need to changed next visit and kichen one dome camera changed working ok</td></tr><tr><td>18-04-2022 10:30:03</td><td>Ravi Rajbhar</td><td>ppm done of CCTV system/epbax system/ access / fire alarm system check all ok working done</td></tr></tbody></table>					Date Time	Technician Name	Remark	22-10-2022 11:03:07	Atique Salmani	Ground floor main entry Smoke Detector cahnged Based changed on third floor /304/306/308/302 Allzones working on healthy condition. 1.Intercom .309 line was dead repunching and instruments end also reconnection from 2 ends switch board to next swich board . 2.306 checked line reconnection form rj 11 and working ok 3.308 instrument to rj 11 female socket cable faulty changed also cable instrument to rj11 changed working ok. 4.108 1st floor staircase to room nmbr 108 cable faulty line ok . Cable need to changed south gate camera new installed but mode didn't changed so again installed old camera need to changed next visit and kichen one dome camera changed working ok	18-04-2022 10:30:03	Ravi Rajbhar	ppm done of CCTV system/epbax system/ access / fire alarm system check all ok working done						
Date Time	Technician Name	Remark																		
22-10-2022 11:03:07	Atique Salmani	Ground floor main entry Smoke Detector cahnged Based changed on third floor /304/306/308/302 Allzones working on healthy condition. 1.Intercom .309 line was dead repunching and instruments end also reconnection from 2 ends switch board to next swich board . 2.306 checked line reconnection form rj 11 and working ok 3.308 instrument to rj 11 female socket cable faulty changed also cable instrument to rj11 changed working ok. 4.108 1st floor staircase to room nmbr 108 cable faulty line ok . Cable need to changed south gate camera new installed but mode didn't changed so again installed old camera need to changed next visit and kichen one dome camera changed working ok																		
18-04-2022 10:30:03	Ravi Rajbhar	ppm done of CCTV system/epbax system/ access / fire alarm system check all ok working done																		