







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE7533																																								
Priority :	Low																																							
Created By :	Admin - Apurva Vajaria																																							
Complaint Mob. No. :	9833444560																																							
Technician Name :	Mayur Yadav		Technician Mobile :	8411951301																																				
Ticket Type :	New Installation	Date & Time :	03-02-2023 04:36:56																																					
Vendor Details :																																								
Company Name/Client Name :	Blue Breeze	Customer's Mobile :	9833444560	Name :	Abhay Mutreja																																			
Address :																																								
Mumbai , , , , Maharashtra																																								
AMC Details :																																								
Expiry Date :	01-01-1970 05:30:00		Type :																																					
Product Name :	Access																																							
Complain :	new installation																																							
Technician Comment :	Boom barrier installation done Both reader installed Exit switch and photo cell installed 22 Tag aaded in controller Working ok Boom barrier resting not slowly.																																							
Complain Operator :	Desktop - Apurva Vajaria																																							
Remark :	Boom barrier installation done Both reader installed Exit switch and photo cell installed 22 Tag aaded in controller Working ok Boom barrier resting not slowly.																																							
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>26-02-2023 03:09:14</td><td>MayurYadav</td><td>Completed</td><td>Boom barrier installation done Both reader installed Exit switch and photo cell installed 22 Tag aaded in controller Working ok Boom barrier resting not slowly.</td><td></td></tr><tr><td>23-02-2023 05:03:18</td><td>MayurYadav</td><td>In Progress</td><td>1 Reader, 1 boom barier install Panel and 1 Reader take to office</td><td></td></tr><tr><td>23-02-2023 10:44:23</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>22-02-2023 10:25:14</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>21-02-2023 09:55:01</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>03-02-2023 04:37:07</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	26-02-2023 03:09:14	MayurYadav	Completed	Boom barrier installation done Both reader installed Exit switch and photo cell installed 22 Tag aaded in controller Working ok Boom barrier resting not slowly.		23-02-2023 05:03:18	MayurYadav	In Progress	1 Reader, 1 boom barier install Panel and 1 Reader take to office		23-02-2023 10:44:23	MayurYadav	New		-	22-02-2023 10:25:14	MayurYadav	New		-	21-02-2023 09:55:01	MayurYadav	New		-	03-02-2023 04:37:07	MayurYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																																				
26-02-2023 03:09:14	MayurYadav	Completed	Boom barrier installation done Both reader installed Exit switch and photo cell installed 22 Tag aaded in controller Working ok Boom barrier resting not slowly.																																					
23-02-2023 05:03:18	MayurYadav	In Progress	1 Reader, 1 boom barier install Panel and 1 Reader take to office																																					
23-02-2023 10:44:23	MayurYadav	New		-																																				
22-02-2023 10:25:14	MayurYadav	New		-																																				
21-02-2023 09:55:01	MayurYadav	New		-																																				
03-02-2023 04:37:07	MayurYadav	New		-																																				

Previous Complain History :	Date Time	Technician Name	Remark
	18-07-2023 11:18:39	Ravi Rajbhar	boom barrier sounding issue relsoved and ok working but bike tag in side slow working and out side proper done but need to change tag said to essl parson
	30-05-2023 01:20:06	Ravi Rajbhar	boom barrier issue resolved and ok working done