

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE8894																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9833444560																			
Technician Name :	Ravi Rajbhar	Technician Mobile :	8080922965																	
Ticket Type :	Complain	Date & Time :	18-07-2023 11:18:39																	
Vendor Details :																				
Company Name/Client Name :	Blue Breeze	Customer's Mobile :	9833444560	Name :	Abhay Mutreja															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00	Type :																		
Product Name :	Access																			
Complain :	Boom Barrier setting issue																			
Technician Comment :	boom barrier sounding issue relsoved and ok working but bike tag in side slow working and out side proper done but need to change tag said to essl parson																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	boom barrier sounding issue relsoved and ok working but bike tag in side slow working and out side proper done but need to change tag said to essl parson																			
Status History :	<table border="1"><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>18-07-2023 08:32:25</td><td>Ravi Rajbhar</td><td>Completed</td><td>boom barrier sounding issue relsoved and ok working but bike tag in side slow working and out side proper done but need to change tag said to essl parson</td><td></td></tr><tr><td>18-07-2023 11:18:46</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	18-07-2023 08:32:25	Ravi Rajbhar	Completed	boom barrier sounding issue relsoved and ok working but bike tag in side slow working and out side proper done but need to change tag said to essl parson		18-07-2023 11:18:46	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																
18-07-2023 08:32:25	Ravi Rajbhar	Completed	boom barrier sounding issue relsoved and ok working but bike tag in side slow working and out side proper done but need to change tag said to essl parson																	
18-07-2023 11:18:46	Ravi Rajbhar	New		-																
Previous Complain History :	<table border="1"><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>30-05-2023 01:20:06</td><td>Ravi Rajbhar</td><td>boom barrier issue resolved and ok working done</td></tr><tr><td>08-03-2023 10:52:26</td><td>PravinJagade</td><td></td></tr></tbody></table>					Date Time	Technician Name	Remark	30-05-2023 01:20:06	Ravi Rajbhar	boom barrier issue resolved and ok working done	08-03-2023 10:52:26	PravinJagade							
Date Time	Technician Name	Remark																		
30-05-2023 01:20:06	Ravi Rajbhar	boom barrier issue resolved and ok working done																		
08-03-2023 10:52:26	PravinJagade																			