


Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

| | | | | | |
|--|---|--------------------------|---|---|---|
| Service Status Details : VE7788 | | | | | |
| Priority : | Low | | | | |
| Created By : | Admin - Apurva Vajaria | | | | |
| Complaint Mob. No. : | 9619209853 | | | | |
| Technician Name : | Siddhesh Chavan | | Technician Mobile : | 8080922985 | |
| Ticket Type : | Complain | Date & Time : | 06-03-2023 10:11:16 | | |
| Vendor Details : | | | | | |
| Company Name/Client Name : | Octavius Cooperative Housing Society Ltd | Customer's Mobile : | 9619209853 | Name : | Amar Ganesh |
| Address : | | | | | |
| Mumbai , , , , Maharashtra | | | | | |
| AMC Details : | | | | | |
| Expiry Date : | 25-08-2020 12:00:00 | | Type : | Non-Comprehensive | |
| Product Name : | CCTV | | | | |
| Complain : | need to do resurvey of cctv | | | | |
| Technician Comment : | all dvr check and report in manual all camera working ok 4 camera no video issue all hdd normal lift NVR view lobby cabling 80 to 90 MTR lamsam and need to send hdmi extender hdmi cable | | | | |
| Complain Operator : | Desktop - Apurva Vajaria | | | | |
| Remark : | all dvr check and report in manual all camera working ok 4 camera no video issue all hdd normal lift NVR view lobby cabling 80 to 90 MTR lamsam and need to send hdmi extender hdmi cable | | | | |
| Status History : | Date Time | Technician Name | Status | Remark | Sign |
| | 06-03-2023 03:30:31 | Siddhesh Chavan | Completed | all dvr check and report in manual all camera working ok 4 camera no video issue all hdd normal lift NVR view lobby cabling 80 to 90 MTR lamsam and need to send hdmi extender hdmi cable |  |
| | 06-03-2023 10:11:25 | Siddhesh Chavan | New | | - |
| Previous Complain History : | Date Time | Technician Name | Remark | | |
| | 27-12-2022 01:01:29 | Atique Salmani | 9 cameras issue resolved by SMPS was hang up due to power consumption so reconnection from SMPS and all cameras working ok. Also lobby back side camera vedo baloon changed box need to changed . | | |
| | 27-12-2022 10:28:23 | Atique Salmani | 2 new ezviz installation done with formatted memory card recording working ok.memory provide by amar sir . | | |