

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE8272																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9820004498																			
Technician Name :	Pravin Jagade		Technician Mobile :	7262044153																
Ticket Type :	Complain	Date & Time :	04-05-2023 05:01:04																	
Vendor Details :																				
Company Name/Client Name :	Sun Mohit Gems	Customer's Mobile :	9820004498	Name :	Anil Pal															
Address :																				
Mumbai , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	tv buller issue need to check																			
Technician Comment :	Lining isshu resolve done																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	Lining isshu resolve done																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>04-05-2023 06:15:43</td><td>PravinJagade</td><td>Completed</td><td>Lining isshu resolve done</td><td></td></tr><tr><td>04-05-2023 05:01:19</td><td>PravinJagade</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	04-05-2023 06:15:43	PravinJagade	Completed	Lining isshu resolve done		04-05-2023 05:01:19	PravinJagade	New		-
Date Time	Technician Name	Status	Remark	Sign																
04-05-2023 06:15:43	PravinJagade	Completed	Lining isshu resolve done																	
04-05-2023 05:01:19	PravinJagade	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>04-05-2023 12:17:49</td><td>PravinJagade</td><td></td></tr><tr><td>24-04-2023 11:27:48</td><td>Atique Salmani</td><td>There is issue in RC pin so refilled RC pin and also give earthing to dvr now working ok In tv 2 hdmi port empty if 5 metr cable lay then it will be proper right now it's working on hdmi to av converter.</td></tr></tbody></table>					Date Time	Technician Name	Remark	04-05-2023 12:17:49	PravinJagade		24-04-2023 11:27:48	Atique Salmani	There is issue in RC pin so refilled RC pin and also give earthing to dvr now working ok In tv 2 hdmi port empty if 5 metr cable lay then it will be proper right now it's working on hdmi to av converter.						
Date Time	Technician Name	Remark																		
04-05-2023 12:17:49	PravinJagade																			
24-04-2023 11:27:48	Atique Salmani	There is issue in RC pin so refilled RC pin and also give earthing to dvr now working ok In tv 2 hdmi port empty if 5 metr cable lay then it will be proper right now it's working on hdmi to av converter.																		