## Vallabh Enterprises

**Regd. Office** : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 Support : | **W** : www.vallabhenterprises.com **E** : vallabhsecure@yahoo.co.in

Service Status Details : VE2814 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9821214520 **No. :** Technician Siddhesh Chavan **Technician Mobile :** 8080922985 Name : **Ticket Type :** Call Basis Date & Time : 11-03-2021 11:17:06 **Vendor Details :** Customer's Mobile : Company R Prakash And 9821214520 Name : Anish Bhai Name/Client Co. Bhoomi Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** CCTV **Complain**: check dvr hdd, recording new one camera install and 12 MTR cabling done and one camera issue resolved Technician **Comment** : Complain Desktop - Apurva Vajaria **Operator** : **Remark** : new one camera install and 12 MTR cabling done and one camera issue resolved

Status History :					
	Date Time	Technician Name	Status	Remark	Sign
	20-03-2021 05:25:00	Siddhesh Chavan	Completed	new one camera install and 12 MTR cabling done and one camera issue resolved	AN
	16-03-2021 07:15:19	Siddhesh Chavan	New		-
	15-03-2021 10:45:20	Siddhesh Chavan	New		-
	12-03-2021 04:21:03	Siddhesh Chavan	Work Pending	Installed Vga to Hdmi converter and its working ok, need to upgrade firmware for Hik connect. one camera is not working so need to change 1 camera. also boss cabin camera greenish issue. Recording is on motion, from 14th Jan to current date. Hdd 500 Gb.	W.8
	12-03-2021 12:17:23	Siddhesh Chavan	Work Pending	8 Ch dvr of Hikvision, 5 cameras connected and 1 camera not working, need to check one camera, and Cat 6 cable from dvr to router need to be traced, Dvr Hdmi output is not working , Vga output is ok.	()AB
	11-03-2021 11:17:49	Siddhesh Chavan	New		-
	11-03-2021 11:17:06	Siddhesh Chavan	New		-
Previous Complain	Date Time	Technician Name	е	Remark	
History :	28-01-2023 09:56:30	Prashant Nikalje	Door lock not working replace power supply		