

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE11775																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9821214520																			
Technician Name :	Neeraj Chauhan		Technician Mobile :	8898885764																
Ticket Type :	AMC visiting	Date & Time :	30-05-2024 04:33:48																	
Vendor Details :																				
Company Name/Client Name :	Bhoomi Enclave "C" Wing	Customer's Mobile :	9821214520	Name :	Anish Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	Ppm																			
Complain :	Access PPM need to do																			
Technician Comment :	Acsecs control system working okk but door alignment not okk carpenter work required																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	Acsecs control system working okk but door alignment not okk carpenter work required																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>30-05-2024 06:07:36</td><td>Neeraj Chauhan</td><td>Client Side</td><td>Acsecs control system working okk but door alignment not okk carpenter work required</td><td></td></tr><tr><td>30-05-2024 04:35:15</td><td>Neeraj Chauhan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	30-05-2024 06:07:36	Neeraj Chauhan	Client Side	Acsecs control system working okk but door alignment not okk carpenter work required		30-05-2024 04:35:15	Neeraj Chauhan	New		-
Date Time	Technician Name	Status	Remark	Sign																
30-05-2024 06:07:36	Neeraj Chauhan	Client Side	Acsecs control system working okk but door alignment not okk carpenter work required																	
30-05-2024 04:35:15	Neeraj Chauhan	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>28-05-2024 06:39:08</td><td>Neeraj Chauhan</td><td>Ppm done all camera working okk</td></tr><tr><td>12-04-2024 01:18:34</td><td>Atique Salmani</td><td>Reopen exit swich and reconnection done from swich side working ok .</td></tr></tbody></table>					Date Time	Technician Name	Remark	28-05-2024 06:39:08	Neeraj Chauhan	Ppm done all camera working okk	12-04-2024 01:18:34	Atique Salmani	Reopen exit swich and reconnection done from swich side working ok .						
Date Time	Technician Name	Remark																		
28-05-2024 06:39:08	Neeraj Chauhan	Ppm done all camera working okk																		
12-04-2024 01:18:34	Atique Salmani	Reopen exit swich and reconnection done from swich side working ok .																		