




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE13136																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	8828427436																			
Technician Name :	Mayur Yadav		Technician Mobile :	8411951301																
Ticket Type :	Complain	Date & Time :	29-10-2024 11:55:57																	
Vendor Details :																				
Company Name/Client Name :	Classic Telecom	Customer's Mobile :	8828427436	Name :	Ashok Bhai															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	VDP																			
Complain :	Site - Raj Realty Miraroad B1104 vdp instll configure panding B 604 vdp install configure pending B 1801 vdp install configure pending B 1602 VDP Complaint																			
Technician Comment :	B-1104/604/1801 Configured B-1602 Outdoor not installed hole was not proper for connector																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	B-1104/604/1801 Configured B-1602 Outdoor not installed hole was not proper for connector																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>29-10-2024 01:54:10</td><td>MayurYadav</td><td>Client Side</td><td>B-1104/604/1801 Configured B-1602 Outdoor not installed hole was not proper for connector</td><td></td></tr><tr><td>29-10-2024 11:57:15</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	29-10-2024 01:54:10	MayurYadav	Client Side	B-1104/604/1801 Configured B-1602 Outdoor not installed hole was not proper for connector		29-10-2024 11:57:15	MayurYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																
29-10-2024 01:54:10	MayurYadav	Client Side	B-1104/604/1801 Configured B-1602 Outdoor not installed hole was not proper for connector																	
29-10-2024 11:57:15	MayurYadav	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>14-01-2025 09:48:05</td><td>PravinJagade</td><td>Hall vdp working proper done. Hall vdp observation. 2 nd vdp new adaptor install working done..</td></tr><tr><td>23-11-2024 07:02:10</td><td>Shiva Meena</td><td>Vdp working and installation done work completed</td></tr></tbody></table>					Date Time	Technician Name	Remark	14-01-2025 09:48:05	PravinJagade	Hall vdp working proper done. Hall vdp observation. 2 nd vdp new adaptor install working done..	23-11-2024 07:02:10	Shiva Meena	Vdp working and installation done work completed						
Date Time	Technician Name	Remark																		
14-01-2025 09:48:05	PravinJagade	Hall vdp working proper done. Hall vdp observation. 2 nd vdp new adaptor install working done..																		
23-11-2024 07:02:10	Shiva Meena	Vdp working and installation done work completed																		