




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE10544</b>					
<b>Priority :</b>	Low				
<b>Created By :</b>	Admin - Apurva Vajaria				
<b>Complaint Mob. No. :</b>	9137852143				
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984	
<b>Ticket Type :</b>	AMC visiting	<b>Date &amp; Time :</b>	15-01-2024 11:12:23		
<b>Vendor Details :</b>					
<b>Company Name/Client Name :</b>	Tivon Park E/F/G/H Wing	<b>Customer's Mobile :</b>	9137852143	<b>Name :</b>	Ashok Yadav
<b>Address :</b>					
Mumbai , , , , Maharashtra					
<b>AMC Details :</b>					
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>		
<b>Product Name :</b>	Ppm				
<b>Complain :</b>	E/F/G/H wing cctv/Intercom ppm need to do				
<b>Technician Comment :</b>	G wi g lift camera issue resolved by reconnection from lift top And G2 intercom connection done working ok And H 802 no one at home after one week And h703 from duct to falte cable missing so user rj6 cable for intercom working ok also I installed phone .				
<b>Complain Operator :</b>	Desktop - Apurva Vajaria				
<b>Remark :</b>	G wi g lift camera issue resolved by reconnection from lift top And G2 intercom connection done working ok And H 802 no one at home after one week And h703 from duct to falte cable missing so user rj6 cable for intercom working ok also I installed phone .				

Status History :	Date Time	Technician Name	Status	Remark	Sign
	19-01-2024 04:06:38	Atique Salmani	Completed	G wi g lift camera issue resolved by reconnection from lift top And G2 intercom connection done working ok And H 802 no one at home after one week And h703 from duct to falte cable missing so user rj6 cable for intercom working ok also I installed phone .	
	19-01-2024 04:06:38	Atique Salmani	Completed	G wi g lift camera issue resolved by reconnection from lift top And G2 intercom connection done working ok And H 802 no one at home after one week And h703 from duct to falte cable missing so user rj6 cable for intercom working ok also I installed phone .	
	19-01-2024 11:13:59	Atique Salmani	New		-
	15-01-2024 06:24:27	Atique Salmani	Work Pending	Efgh ppm done 802 intercom painding bec client didn't allow and h wing 2 4*4 box need to changed and also f wing lift cable faulty and g wing lift camera power issue not coming need to recheck with lift person .	
	15-01-2024 11:12:32	Atique Salmani	New		-
Previous Complain History :	Date Time	Technician Name	Remark		
	31-01-2024 11:39:50	Shiva Meena	Lift cabling work completed and camera install done 80 mtr cabling done H - 802 intercom install done		
	13-01-2024 01:36:02	Atique Salmani	G wing 1 camera off issue resolved		