




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE10450																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	8169697919																			
Technician Name :	Yogesh Desai		Technician Mobile :	8080922963																
Ticket Type :	Complain	Date & Time :	05-01-2024 12:34:20																	
Vendor Details :																				
Company Name/Client Name :	Dun Apts	Customer's Mobile :	8169697919	Name :	Atul Sir															
Address :																				
Mumbai , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	Some cover has fallen down need to install the same																			
Technician Comment :	Camera housing cover was blown coz of wind . Cover has been put again on camera.																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	Camera housing cover was blown coz of wind . Cover has been put again on camera.																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>05-01-2024 03:45:31</td><td>YogeshDesai</td><td>Completed</td><td>Camera housing cover was blown coz of wind . Cover has been put again on camera.</td><td></td></tr><tr><td>05-01-2024 03:43:30</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	05-01-2024 03:45:31	YogeshDesai	Completed	Camera housing cover was blown coz of wind . Cover has been put again on camera.		05-01-2024 03:43:30	YogeshDesai	New		-
Date Time	Technician Name	Status	Remark	Sign																
05-01-2024 03:45:31	YogeshDesai	Completed	Camera housing cover was blown coz of wind . Cover has been put again on camera.																	
05-01-2024 03:43:30	YogeshDesai	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>04-01-2024 10:25:48</td><td>Sonu Kumar</td><td>Show recording seen by Pandey ji</td></tr><tr><td>15-12-2023 10:31:11</td><td>Atique Salmani</td><td>1001 /2 allready working only chek form flate side and timing resetbecz it was 15 mnt delay so from 1st floor system crone 1st port set working ok.</td></tr></tbody></table>					Date Time	Technician Name	Remark	04-01-2024 10:25:48	Sonu Kumar	Show recording seen by Pandey ji	15-12-2023 10:31:11	Atique Salmani	1001 /2 allready working only chek form flate side and timing resetbecz it was 15 mnt delay so from 1st floor system crone 1st port set working ok.						
Date Time	Technician Name	Remark																		
04-01-2024 10:25:48	Sonu Kumar	Show recording seen by Pandey ji																		
15-12-2023 10:31:11	Atique Salmani	1001 /2 allready working only chek form flate side and timing resetbecz it was 15 mnt delay so from 1st floor system crone 1st port set working ok.																		