## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

Service Status Details : VE10618							
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	8169697919						
Technician Name :	Atique Salmani		Technicia	Technician Mobile :		8080922984	
Ticket Type :	Complain Date & Time :		23-01-202	23-01-2024 01:18:58			
Vendor Details :							
Company Name/Client Name :	Dun Apts	Customer's Mobile	e: 81696979	19	Name :	Atul Sir	
Address:							
Mumbai,,,,Maharashtra							
AMC Details :							
Expiry Date :	01-01-1970 05:30:00		Type:	Type:			
<b>Product Name :</b>	CCTV						
Complain:	some cameras issue black and white						
Technician Comment :	All cameras issue resolved maine gate camera was more disturbance so used new SMPS for gate camera and $11$ nmbr camera need to changed with box and also $2$ more box need to changed .						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	All cameras issue resolved maine gate camera was more disturbance so used new SMPS for gate camera and $11$ nmbr camera need to changed with box and also $2$ more box need to changed .						
<b>Status History:</b>	Date Time	Technician Name	Status	Re	Remark Si		
	24-01-2024 05:23:12	Atique Salmani	Completed	All cameras issue resolved maine gate camera was more disturbance so used new SMPS for gate camera and 11 nmbr camera need to changed with box and also 2 more box need to changed.		Û	
	24-01-2024 10:24:09	Atique Salmani	New			-	
	23-01-2024 06:19:33	Atique Salmani	Work Pending	also camera l issue pending	olackand white	Lat	
	23-01-2024 01:19:03	Atique Salmani	New			-	

Previous Complain History :	Date Time	Technician Name	Remark	
	06-02-2024 10:26:33	Atique Salmani	Hikvision dvr was off so showing no signal becz SMPS was blinking 16 port SMPS 8 port ok and 8 blinking dvr also connect with this so used other existing SMPS working ok.also 2 camera issue resolved.	
	24-01-2024 12:14:12	Atique Salmani	Main gate camera need to give camera end SMPS and observe abecz it's long length.	