Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status De	tails: VE10767					
Priority:	Low					
Created By:	Admin - Apurva Vajaria					
Complaint Mob. No. :	8169697919					
Technician Name :	Atique Salmani		Techn	nician Mobile : 80809229		
Ticket Type :	Complain	Date & Time :	06-02-2024 10:26:33		•	
Vendor Details :			•			-
Company Name/Client Name :	Dun Apts	Customer's Mobil	e: 81696	97919	Name :	Atul Sir
Address:						
Mumbai , , , , Mal	narashtra					
AMC Details :						
Expiry Date :	01-01-1970 05:30:0	00	Type:			
Product Name :	CCTV					
Complain :	lobby Tv no signal issue and outside TV 2 camera showing no video					
Technician Comment :	Hikvision dvr was off so showing no signal becz SMPS was blinking 16 port SMPS 8 port ok and 8 blinking dvr also connect with this so used other existing SMPS working ok.also 2 camera issue resolved.					
Complain Operator :	Desktop - Apurva Vajaria					
Remark:	Hikvision dvr was off so showing no signal becz SMPS was blinking 16 port SMPS 8 port ok and 8 blinking dvr also connect with this so used other existing SMPS working ok.also 2 camera issue resolved.					
Status History :	Date Time	Technician Name	Status	Remark		Sign
	06-02-2024 03:50:00	Atique Salmani	Completed	Hikvision dvr was off so showing no signal becz SMPS was blinking 16 port SMPS 8 port ok and 8 blinking dvr also connect with this so used other existing SMPS working ok.also 2 camera issue resolved.		946
	06-02-2024 01:35:27	Atique Salmani	New	-		-
Previous Complain History :	Date Time	Technician Name		Remark		
	24-01-2024 12:14:12	Atique Salmani		Main gate camera need to give camera end SMPS and observe abecz it's long length.		
	23-01-2024 01:18:58	Atique Salmani	disturbanc	All cameras issue resolved maine gate camera was more disturbance so used new SMPS for gate camera and 11 nmbr camera need to changed with box and also 2 more box need to changed.		