




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE5380</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	8169697919																								
<b>Technician Name :</b>	Siddhesh Chavan		<b>Technician Mobile :</b>	8080922985																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	04-05-2022 06:36:57																						
<b>Vendor Details :</b>																									
Company Name/Client Name :	Dun Apts	Customer's Mobile :	8169697919	Name :	Atul Sir																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
<b>Product Name :</b>	Intercom																								
<b>Complain :</b>	flat no 206 / 601 intercom issue																								
<b>Technician Comment :</b>	206 recontion and intrcom issue resolved 601 line working ok no phone 705 phone keypad issue and line working ok																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	206 recontion and intrcom issue resolved 601 line working ok no phone 705 phone keypad issue and line working ok																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>05-05-2022 11:42:48</td><td>Siddhesh Chavan</td><td>Completed</td><td>206 recontion and intrcom issue resolved 601 line working ok no phone 705 phone keypad issue and line working ok</td><td></td></tr><tr><td>04-05-2022 06:37:12</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>04-05-2022 06:36:57</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	05-05-2022 11:42:48	Siddhesh Chavan	Completed	206 recontion and intrcom issue resolved 601 line working ok no phone 705 phone keypad issue and line working ok		04-05-2022 06:37:12	Siddhesh Chavan	New		-	04-05-2022 06:36:57	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																					
05-05-2022 11:42:48	Siddhesh Chavan	Completed	206 recontion and intrcom issue resolved 601 line working ok no phone 705 phone keypad issue and line working ok																						
04-05-2022 06:37:12	Siddhesh Chavan	New		-																					
04-05-2022 06:36:57	Siddhesh Chavan	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>23-03-2022 10:22:48</td><td>Siddhesh Chavan</td><td>main gate intercom issue resolved and 702 204 line ok phone issue and 1001 line ok 605 duck side line working ok and flat one work and all line working ok</td></tr><tr><td>23-12-2021 10:42:57</td><td>YogeshDesai</td><td>flat no 1003 phone issue line ok have checked with other phone. main gate intercom cable was cut rejoined line working ok .</td></tr></tbody></table>					Date Time	Technician Name	Remark	23-03-2022 10:22:48	Siddhesh Chavan	main gate intercom issue resolved and 702 204 line ok phone issue and 1001 line ok 605 duck side line working ok and flat one work and all line working ok	23-12-2021 10:42:57	YogeshDesai	flat no 1003 phone issue line ok have checked with other phone. main gate intercom cable was cut rejoined line working ok .											
Date Time	Technician Name	Remark																							
23-03-2022 10:22:48	Siddhesh Chavan	main gate intercom issue resolved and 702 204 line ok phone issue and 1001 line ok 605 duck side line working ok and flat one work and all line working ok																							
23-12-2021 10:42:57	YogeshDesai	flat no 1003 phone issue line ok have checked with other phone. main gate intercom cable was cut rejoined line working ok .																							