




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE8525</b>																				
<b>Priority :</b>	Low																			
<b>Created By :</b>	Admin - Apurva Vajaria																			
<b>Complaint Mob. No. :</b>	8169697919																			
<b>Technician Name :</b>	Kalpesh Subhash Gurav		<b>Technician Mobile :</b>	8879684054																
<b>Ticket Type :</b>	AMC visiting	<b>Date &amp; Time :</b>	08-06-2023 02:51:30																	
<b>Vendor Details :</b>																				
<b>Company Name/Client Name :</b>	Dun Apts	<b>Customer's Mobile :</b>	8169697919	<b>Name :</b>	Atul Sir															
<b>Address :</b>																				
Mumbai , , , , Maharashtra																				
<b>AMC Details :</b>																				
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>																	
<b>Product Name :</b>	Ppm																			
<b>Complain :</b>	CCTV/intercom PPM Need to do																			
<b>Technician Comment :</b>	Main Gate Camera no. 7 Cable Faulty Required 170 meter cable. Best Sub Station Camera No. 15 cable Faulty Required 50 meter cable. Camera no. 9 Camera sensor issue Required New Bullet Camera. And Required 15 pair video balloon for Proper dressing DVR And Camera side																			
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																			
<b>Remark :</b>	Main Gate Camera no. 7 Cable Faulty Required 170 meter cable. Best Sub Station Camera No. 15 cable Faulty Required 50 meter cable. Camera no. 9 Camera sensor issue Required New Bullet Camera. And Required 15 pair video balloon for Proper dressing DVR And Camera side																			
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>08-06-2023 06:32:47</td><td>Kalpesh SubhashGurav</td><td>Completed</td><td>Main Gate Camera no. 7 Cable Faulty Required 170 meter cable. Best Sub Station Camera No. 15 cable Faulty Required 50 meter cable. Camera no. 9 Camera sensor issue Required New Bullet Camera. And Required 15 pair video balloon for Proper dressing DVR And Camera side</td><td></td></tr><tr><td>08-06-2023 02:51:36</td><td>Kalpesh SubhashGurav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	08-06-2023 06:32:47	Kalpesh SubhashGurav	Completed	Main Gate Camera no. 7 Cable Faulty Required 170 meter cable. Best Sub Station Camera No. 15 cable Faulty Required 50 meter cable. Camera no. 9 Camera sensor issue Required New Bullet Camera. And Required 15 pair video balloon for Proper dressing DVR And Camera side		08-06-2023 02:51:36	Kalpesh SubhashGurav	New		-
Date Time	Technician Name	Status	Remark	Sign																
08-06-2023 06:32:47	Kalpesh SubhashGurav	Completed	Main Gate Camera no. 7 Cable Faulty Required 170 meter cable. Best Sub Station Camera No. 15 cable Faulty Required 50 meter cable. Camera no. 9 Camera sensor issue Required New Bullet Camera. And Required 15 pair video balloon for Proper dressing DVR And Camera side																	
08-06-2023 02:51:36	Kalpesh SubhashGurav	New		-																

Previous Complain History :			
	<b>Date Time</b>	<b>Technician Name</b>	<b>Remark</b>
	03-06-2023 04:56:54	Shiva Meena	300 cebal and get camera cebal folty and 16 no. Camera cebal pawer isu band chalu aal camera ok wark complete
	24-05-2023 02:02:15	Kalpesh SubhashGurav	406 - Intercom line switched on ( The flat owner will bring the phone ) 703 - Intercom connection is not required. 706 - Line OK 104 - Line OK 1102 - Lock 204 - Intercom line switched on ( The flat owner will bring the phone) Main Lobby Security Ext.91/92 Roset box Connected and turned on.