




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE8157</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9158640778																								
<b>Technician Name :</b>	Ravi Rajbhar		<b>Technician Mobile :</b>	8080922965																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	19-04-2023 11:01:02																						
<b>Vendor Details :</b>																									
<b>Company Name/Client Name :</b>	Sai Akashdeep Chs Ltd	<b>Customer's Mobile :</b>	9158640778	<b>Name :</b>	Aziza Madam																				
<b>Address :</b>																									
Mumbai , , , 400064 , Maharashtra																									
<b>AMC Details :</b>																									
<b>Expiry Date :</b>	30-11-2020 12:00:00		<b>Type :</b>	Non-Comprehensive																					
<b>Product Name :</b>	VDP																								
<b>Complain :</b>	VDP of Flat No. 2002 is not working properly. Also check all Flat's VDP system.																								
<b>Technician Comment :</b>	vdp 2001 lobby camera no video issue resolved and ok working done 1201 lobby camera no video issue resolved and ok working done and 20 floor next time need to change distributor 402 intercom also ok working																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	vdp 2001 lobby camera no video issue resolved and ok working done 1201 lobby camera no video issue resolved and ok working done and 20 floor next time need to change distributor 402 intercom also ok working																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>20-04-2023 11:53:55</td><td>Ravi Rajbhar</td><td>Completed</td><td>vdp 2001 lobby camera no video issue resolved and ok working done 1201 lobby camera no video issue resolved and ok working done and 20 floor next time need to change distributor 402 intercom also ok working</td><td></td></tr><tr><td>20-04-2023 10:01:43</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>19-04-2023 11:01:08</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	20-04-2023 11:53:55	Ravi Rajbhar	Completed	vdp 2001 lobby camera no video issue resolved and ok working done 1201 lobby camera no video issue resolved and ok working done and 20 floor next time need to change distributor 402 intercom also ok working		20-04-2023 10:01:43	Ravi Rajbhar	New		-	19-04-2023 11:01:08	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
20-04-2023 11:53:55	Ravi Rajbhar	Completed	vdp 2001 lobby camera no video issue resolved and ok working done 1201 lobby camera no video issue resolved and ok working done and 20 floor next time need to change distributor 402 intercom also ok working																						
20-04-2023 10:01:43	Ravi Rajbhar	New		-																					
19-04-2023 11:01:08	Ravi Rajbhar	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>11-05-2023 03:33:02</td><td>ChandanYadav</td><td>One camera society loby install.</td></tr><tr><td>20-04-2023 11:51:26</td><td>Ravi Rajbhar</td><td></td></tr></tbody></table>					Date Time	Technician Name	Remark	11-05-2023 03:33:02	ChandanYadav	One camera society loby install.	20-04-2023 11:51:26	Ravi Rajbhar												
Date Time	Technician Name	Remark																							
11-05-2023 03:33:02	ChandanYadav	One camera society loby install.																							
20-04-2023 11:51:26	Ravi Rajbhar																								