


# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE12139</b>					
<b>Priority :</b>	Low				
<b>Created By :</b>	Admin - Apurva Vajaria				
<b>Complaint Mob. No. :</b>	7400084949				
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984	
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	13-07-2024 02:43:04		
<b>Vendor Details :</b>					
<b>Company Name/Client Name :</b>	JB Boda Pvt Ltd Churchgate	<b>Customer's Mobile :</b>	7400084949	<b>Name :</b>	Bhavesh Sir
<b>Address :</b>					
Mumbai , , , , Maharashtra					
<b>AMC Details :</b>					
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>		
<b>Product Name :</b>	Fire				
<b>Complain :</b>	MAKER BHAVAN 7th / 8th / 9th & 1st floor - Fire PPM need to do				
<b>Technician Comment :</b>	9thfloor Jb. Boda 9th floor boath battery need to changed becz showing 21 volta and single battery 10.96 total 16 detector with mcp n hooter . 8 floor hooter to mcp + loop cable cut Missing cable need to lay new cabling 7 floor total 18 detector with hooter n mcp also battery wiring fault so reset working ok. Under observation. 2nd floor total 14 detector with hooter n mcp all ok . 1st floor all system dead total 22 detector Mcp+ 1 hooter combined . Basement GST pannel all working ok With 7 detector and 1 mcp one hooter .				
<b>Complain Operator :</b>	Desktop - Apurva Vajaria				
<b>Remark :</b>	9thfloor Jb. Boda 9th floor boath battery need to changed becz showing 21 volta and single battery 10.96 total 16 detector with mcp n hooter . 8 floor hooter to mcp + loop cable cut Missing cable need to lay new cabling 7 floor total 18 detector with hooter n mcp also battery wiring fault so reset working ok. Under observation. 2nd floor total 14 detector with hooter n mcp all ok . 1st floor all system dead total 22 detector Mcp+ 1 hooter combined . Basement GST pannel all working ok With 7 detector and 1 mcp one hooter .				

Status History :					
	Date Time	Technician Name	Status	Remark	Sign
	13-07-2024 05:41:52	Atique Salmani	Completed	9thfloor Jb. Boda 9th floor boath battery need to changed bec showing 21 volta and single battery 10.96 total 16 detector with mcp n hooter . 8 floor hooter to mcp + loop cable cut Missing cable need to lay new cabling 7 floor total 18 detector with hooter n mcp also battery wiring fault so reset working ok. Under observation. 2nd floor total 14 detector with hooter n mcp all ok . 1st floor all system dead total 22 detector Mcp+ 1 hooter combined . Basement GST pannel all working ok With 7 detector and 1 mcp one hooter .	
	13-07-2024 02:43:12	Atique Salmani	New		-
Previous Complain History :					
	Date Time	Technician Name	Remark		
	09-09-2024 02:47:40	Shiva Meena	Tirgar cheng work completed and old tirgar work completed		
	03-08-2024 03:13:06	Shiva Meena	Fair testing and done 8 miter cebling work completed		