




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE14133																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9820223640																								
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																					
Ticket Type :	Complain	Date & Time :	21-02-2025 02:40:36																						
Vendor Details :																									
Company Name/Client Name :	Shimoni CHS Ltd	Customer's Mobile :	9820223640	Name :	Bhavesh Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	CCTV																								
Complain :	lift 2 cameras off issue																								
Technician Comment :	There was extention board swich was off so cameras also off on its working ok boath lift .																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	There was extention board swich was off so cameras also off on its working ok boath lift .																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>25-02-2025 12:16:10</td><td>Atique Salmani</td><td>Completed</td><td>There was extention board swich was off so cameras also off on its working ok boath lift .</td><td></td></tr><tr><td>25-02-2025 11:03:59</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>21-02-2025 05:37:47</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	25-02-2025 12:16:10	Atique Salmani	Completed	There was extention board swich was off so cameras also off on its working ok boath lift .		25-02-2025 11:03:59	Atique Salmani	New		-	21-02-2025 05:37:47	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
25-02-2025 12:16:10	Atique Salmani	Completed	There was extention board swich was off so cameras also off on its working ok boath lift .																						
25-02-2025 11:03:59	Atique Salmani	New		-																					
21-02-2025 05:37:47	Atique Salmani	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>15-04-2025 04:06:38</td><td>TauseephRaza</td><td>cameras off issue resolved</td></tr><tr><td>17-02-2025 12:20:28</td><td>Atique Salmani</td><td></td></tr></tbody></table>					Date Time	Technician Name	Remark	15-04-2025 04:06:38	TauseephRaza	cameras off issue resolved	17-02-2025 12:20:28	Atique Salmani												
Date Time	Technician Name	Remark																							
15-04-2025 04:06:38	TauseephRaza	cameras off issue resolved																							
17-02-2025 12:20:28	Atique Salmani																								