## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

E: vallabhsecure@yahoo.co.in							
Service Status Det	ails : VE11276						
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob.	9167344895						
Technician Name :	Sonu Kumar		Technici	<b>Technician Mobile :</b> 84		8454016444	
Ticket Type :	Complain	Date & Time :	01-04-2024 12:59:10				
Vendor Details :			•				
Company Name/Client Name :	Konark CHS Ltd	Customer's Mobile	le: 9167344895		Name :	Bijal Sir	
Address:							
Mumbai,,,,Mah	arashtra						
AMC Details :							
Expiry Date :	31-03-2021 12:00:	00	Type:		Comprehensive		
<b>Product Name:</b>	CCTV						
Complain:	Lobby new bullet camera need to install and flat no. 403 intercom issue						
Technician Comment :	1 camera off issue resolved working ok and 403/503 intercom issue resolved working ok and 1 new camera installation done						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	1 camera off issue resolved working ok and 403/503 intercom issue resolved working ok and 1 new camera installation done						
<b>Status History:</b>	Date Time	Technician Name	Status	Remark		Sign	
	01-04-2024 04:15:03	Sonu Kumar	Completed	1 camera off issue resolved working ok and 403/503 intercom issue resolved working ok and 1 new camera installation done		Mikin	
	01-04-2024 01:27:13	Sonu Kumar	New			-	
Previous Complain History:	Date Time	Technician Name	Remark				
	30-03-2024 12:27:22	Sonu Kumar	01.04.2024 - Sonu/Prashant - 1 camera off issue resolved working ok and 403/503 intercom issue resolved working ok and 1 new camera installation done				
	21-03-2024 01:11:13	Ravi Rajbhar	one cmaera car parking area side need to change bcz Bullat camera faulty and remove and hondover to brijal sir 01.04.2024 - Sonu/Prashant - 1 camera off issue resolved working ok and 403/503 intercom issue resolved working ok and 1 new camera installation done				