




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE14302																																			
Priority :	Low																																		
Created By :	Admin - Apurva Vajaria																																		
Complaint Mob. No. :	9167344895																																		
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																															
Ticket Type :	Complain	Date & Time :	17-03-2025 02:25:47																																
Vendor Details :																																			
Company Name/Client Name :	Konark CHS Ltd	Customer's Mobile :	9167344895	Name :	Bijal Sir																														
Address :																																			
Mumbai , , , , Maharashtra																																			
AMC Details :																																			
Expiry Date :	31-03-2021 12:00:00		Type :	Comprehensive																															
Product Name :	CCTV																																		
Complain :	watchmen cabin phone issue																																		
Technician Comment :	Card issue then card remove and take to office																																		
Complain Operator :	Desktop - Apurva Vajaria																																		
Remark :	Card issue then card remove and take to office 09.04.2025 Ravi visited and new card installed and faulty return to client now intercom system working ok																																		
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>12-04-2025 01:02:33</td><td>Ravi Rajbhar</td><td>Completed</td><td></td><td>-</td></tr><tr><td>09-04-2025 10:40:20</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>21-03-2025 11:39:52</td><td>Ravi Rajbhar</td><td>Work Pending</td><td>Card issue then card remove and take to office</td><td></td></tr><tr><td>20-03-2025 06:42:44</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>17-03-2025 02:25:56</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	12-04-2025 01:02:33	Ravi Rajbhar	Completed		-	09-04-2025 10:40:20	Ravi Rajbhar	New		-	21-03-2025 11:39:52	Ravi Rajbhar	Work Pending	Card issue then card remove and take to office		20-03-2025 06:42:44	Ravi Rajbhar	New		-	17-03-2025 02:25:56	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																															
12-04-2025 01:02:33	Ravi Rajbhar	Completed		-																															
09-04-2025 10:40:20	Ravi Rajbhar	New		-																															
21-03-2025 11:39:52	Ravi Rajbhar	Work Pending	Card issue then card remove and take to office																																
20-03-2025 06:42:44	Ravi Rajbhar	New		-																															
17-03-2025 02:25:56	Ravi Rajbhar	New		-																															
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>07-04-2025 11:23:15</td><td>Ravi Rajbhar</td><td>09.04.2025 - Ravi visited and recording issue solved</td></tr><tr><td>21-03-2025 07:14:00</td><td>Ravi Rajbhar</td><td>One cmaera issue resolved and ok working done camera side bnc pin change and cable check And new instrument install and ok working done against faulty</td></tr></tbody></table>					Date Time	Technician Name	Remark	07-04-2025 11:23:15	Ravi Rajbhar	09.04.2025 - Ravi visited and recording issue solved	21-03-2025 07:14:00	Ravi Rajbhar	One cmaera issue resolved and ok working done camera side bnc pin change and cable check And new instrument install and ok working done against faulty																					
Date Time	Technician Name	Remark																																	
07-04-2025 11:23:15	Ravi Rajbhar	09.04.2025 - Ravi visited and recording issue solved																																	
21-03-2025 07:14:00	Ravi Rajbhar	One cmaera issue resolved and ok working done camera side bnc pin change and cable check And new instrument install and ok working done against faulty																																	