Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE350 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9167344895 **No. :** Technician Mahindra Prajapati **Technician Mobile :** 8080922975 Name : Complain 16-09-2019 02:41:07 **Ticket Type :** Date & Time : **Vendor Details :** Company Konark CHS Ltd Customer's Mobile : 9167344895 Bijal Sir Name : Name/Client Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** Time And Attendance **Complain**: cannot read fingerprint one biometric installation is done and 4 person finger done Technician **Comment**: Complain Desktop - Apurva Vajaria **Operator** : **Remark** : one biometric installation is done and 4 person finger done **Status History : Date Time Technician Name** Status Remark Sign MahindraPrajapati 05-10-2019 05:24:33 Completed one biometric energy installation is done and 4 person finger done 05-10-2019 05:22:23 MahindraPrajapati New 16-09-2019 05:52:42 MahindraPrajapati In Progress bio matric display issue in the second under repair 16-09-2019 03:39:16 MahindraPrajapati New 16-09-2019 02:41:08 MahindraPrajapati New Previous **Technician Name** Remark **Date Time** Complain **History** : 06-11-2019 11:49:02 AnilYadav Reception camera not working because connection was dead. I do reconnection camera is working condition now. And 1st,2nd,3rd floors camera lens clean now good camera viewing. 19-10-2019 10:01:47 Ravi Rajbhar 302.502 intercom issue reslvoed and ok working done and 101 and 103 wering Breck and 101 port issue