## Vallabh Enterprises

**Regd. Office** : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE13030 Low **Priority** : **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9224657132 **No. : Technician Name** Siddhesh Chavan **Technician Mobile** 8080922985 Complain Date & Time : 17-10-2024 05:59:27 **Ticket Type : Vendor Details :** Bhoomi Customer's 9224657132 Bipin Sir Company Name : Name/Client Name Association Mobile : Address : Mumbai,,,, Maharashtra **AMC Details :** 31-03-2021 12:00:00 Expiry Date : Type : Non-Comprehensive **Product Name :** CCTV 1 standby bullet camera need to install and faulty bullet camera need to collect **Complain**: Stand by Camera install And old Camera take to office repring Technician **Comment** : Complain Desktop - Apurva Vajaria **Operator** : **Remark :** Stand by Camera install And old Camera take to office repring **Status History : Date Time Technician Name** Status Remark Sign 17-10-2024 06:49:23 Siddhesh Chavan Completed Stand by Camera install And old Camera take to 2177101 office repring d 17-10-2024 05:59:36 Siddhesh Chavan New **Previous Date Time Technician Name** Remark **Complain History** 29-10-2024 ChandanYadav C wing main gate side camera install done.camera working ok. 11:45:16 11-09-2024 ChandanYadav E wing back side camera pinkish issue solve and main gate 01:40:21 side camera pinkish issue found also installed client to same. 11/10/24 timing 6:48 NVR gone off due to spike guard power off and due to recording also not done and 16/10/24 timing 4:50 spike guard power on and NVR working ok