Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

E : valiablisecure@yar.	100,00,111								
Service Status De	tails: VE4943								
Priority:	Low								
Created By:	Admin - Apurva Vajaria								
Complaint Mob.	9820053157								
Technician Name :	Yogesh Desai			Te	echnician M	8080922963			
Ticket Type :	Complain Date		& Time:	05-03-2022 10:26:00					
Vendor Details :									
Company Name/Client Name :	Captain Kohal Custo		ner's Mobile	9	9820053157		Name :	Captain Kohal	
Address:									
Mumbai , , , , Mal	harashtra								
AMC Details :									
Expiry Date :	01-01-1970 05:30:00			Type:					
Product Name:	CCTV								
Complain:	beep sound issue								
Technician Comment :	beep sound of video loss is now off two cameras are removed from terrace from client for renovation purpose.all camera working ok.								
Complain Operator :	Desktop - Apurva Vajaria								
Remark:	beep sound of video loss is now off two cameras are removed from terrace from client for renovation purpose.all camera working ok.								
Status History :	Date Time		Technician Name		Status	Remark			Sign
	07-03-2022 12:24:40		YogeshDesai		Completed	beep sound of video loss is now off two cameras are removed from terrace fror client for renovation purpose.all camera working ok.			
	07-03-2022 12:20:12		YogeshDesai		New				-
	07-03-2022 10:56:36		YogeshDesai		New				-
	05-03-2022 10:26:34		YogeshDesai		New			4	-
	05-03-2022 10:26:00 YogeshDesa		YogeshDesai		New	<u></u>			-
Previous Complain History :	Date Time	Tecl	hnician Name				Remark		
	21-01-2022 10:07:08	Atio	que Salmani	one old camera installed and camera nmbr 6 on off issue bresolved it's under observation and camera nmbr 12 reconction and all working ok.3 bnc used . total 4 cames .issue resolved.					
	07-01-2022 05:52:28	Atio	que Salmani	3 ,	3 cameras changed and dvr end also 2 bnc changed and all working ok. old cameras hand over to Aryan \sin .				