







# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE7416</b>																																			
<b>Priority :</b>	Low																																		
<b>Created By :</b>	Admin - Apurva Vajaria																																		
<b>Complaint Mob. No. :</b>	9884958343																																		
<b>Technician Name :</b>	Mayur Yadav		<b>Technician Mobile :</b>	8411951301																															
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	19-01-2023 02:12:14																																
<b>Vendor Details :</b>																																			
Company Name/Client Name :	Bombay Dyeing Worli	Customer's Mobile :	9884958343	Name :	Chandraraja Sir																														
<b>Address :</b>																																			
Mumbai , , , , Maharashtra																																			
<b>AMC Details :</b>																																			
Expiry Date :	31-07-2020 12:00:00		Type :	Comprehensive																															
<b>Product Name :</b>	Access																																		
<b>Complain :</b>	need to add in Promoters main door new 3 Access card																																		
<b>Technician Comment :</b>	One card added in both device Online in Rajiv sir mobile done																																		
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																																		
<b>Remark :</b>	One card added in both device Online in Rajiv sir mobile done																																		
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>31-01-2023 11:40:23</td><td>MayurYadav</td><td>Completed</td><td>One card added in both device Online in Rajiv sir mobile done</td><td></td></tr><tr><td>31-01-2023 10:20:05</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>23-01-2023 12:35:25</td><td>MayurYadav</td><td>Work Pending</td><td>Four new cards not added in device inside door</td><td></td></tr><tr><td>23-01-2023 09:40:14</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>19-01-2023 02:12:24</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	31-01-2023 11:40:23	MayurYadav	Completed	One card added in both device Online in Rajiv sir mobile done		31-01-2023 10:20:05	MayurYadav	New		-	23-01-2023 12:35:25	MayurYadav	Work Pending	Four new cards not added in device inside door		23-01-2023 09:40:14	MayurYadav	New		-	19-01-2023 02:12:24	MayurYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																															
31-01-2023 11:40:23	MayurYadav	Completed	One card added in both device Online in Rajiv sir mobile done																																
31-01-2023 10:20:05	MayurYadav	New		-																															
23-01-2023 12:35:25	MayurYadav	Work Pending	Four new cards not added in device inside door																																
23-01-2023 09:40:14	MayurYadav	New		-																															
19-01-2023 02:12:24	MayurYadav	New		-																															
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>11-02-2023 10:06:28</td><td>Ravi Rajbhar</td><td>Vip lift door access check temper beep sound issue resolved but divice under observation 2-3 day Bcz divice hang also then power supply change next time under observation</td></tr><tr><td>09-02-2023 11:02:18</td><td>MayurYadav</td><td>VIP lift entrance access card reader issue solve device temper alarm remove</td></tr></tbody></table>					Date Time	Technician Name	Remark	11-02-2023 10:06:28	Ravi Rajbhar	Vip lift door access check temper beep sound issue resolved but divice under observation 2-3 day Bcz divice hang also then power supply change next time under observation	09-02-2023 11:02:18	MayurYadav	VIP lift entrance access card reader issue solve device temper alarm remove																					
Date Time	Technician Name	Remark																																	
11-02-2023 10:06:28	Ravi Rajbhar	Vip lift door access check temper beep sound issue resolved but divice under observation 2-3 day Bcz divice hang also then power supply change next time under observation																																	
09-02-2023 11:02:18	MayurYadav	VIP lift entrance access card reader issue solve device temper alarm remove																																	