

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE7581																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9884958343																			
Technician Name :	Mayur Yadav		Technician Mobile :	8411951301																
Ticket Type :	Complain	Date & Time :	09-02-2023 11:02:18																	
Vendor Details :																				
Company Name/Client Name :	Bombay Dyeing Worli	Customer's Mobile :	9884958343	Name :	Chandraraja Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	31-07-2020 12:00:00		Type :	Comprehensive																
Product Name :	Access																			
Complain :	vip lift main entrance door access card reader is giving continuous beep sound																			
Technician Comment :	VIP lift entrance access card reader issue solve device temper alarm remove																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	VIP lift entrance access card reader issue solve device temper alarm remove																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>09-02-2023 11:08:19</td><td>MayurYadav</td><td>Completed</td><td>VIP lift entrance access card reader issue solve device temper alarm remove</td><td></td></tr><tr><td>09-02-2023 11:02:26</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	09-02-2023 11:08:19	MayurYadav	Completed	VIP lift entrance access card reader issue solve device temper alarm remove		09-02-2023 11:02:26	MayurYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																
09-02-2023 11:08:19	MayurYadav	Completed	VIP lift entrance access card reader issue solve device temper alarm remove																	
09-02-2023 11:02:26	MayurYadav	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>11-02-2023 10:06:28</td><td>Ravi Rajbhar</td><td>Vip lift door access check temper beep sound issue resolved but divice under observation 2-3 day Bcz divice hang also then power supply change next time under observation</td></tr><tr><td>09-02-2023 10:55:15</td><td></td><td></td></tr></tbody></table>					Date Time	Technician Name	Remark	11-02-2023 10:06:28	Ravi Rajbhar	Vip lift door access check temper beep sound issue resolved but divice under observation 2-3 day Bcz divice hang also then power supply change next time under observation	09-02-2023 10:55:15								
Date Time	Technician Name	Remark																		
11-02-2023 10:06:28	Ravi Rajbhar	Vip lift door access check temper beep sound issue resolved but divice under observation 2-3 day Bcz divice hang also then power supply change next time under observation																		
09-02-2023 10:55:15																				