




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE7605</b>																				
<b>Priority :</b>	Low																			
<b>Created By :</b>	Admin - Apurva Vajaria																			
<b>Complaint Mob. No. :</b>	9884958343																			
<b>Technician Name :</b>	Ravi Rajbhar		<b>Technician Mobile :</b>	8080922965																
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	11-02-2023 10:06:28																	
<b>Vendor Details :</b>																				
<b>Company Name/Client Name :</b>	Bombay Dyeing Worli	<b>Customer's Mobile :</b>	9884958343	<b>Name :</b>	Chandraraja Sir															
<b>Address :</b>																				
Mumbai , , , , Maharashtra																				
<b>AMC Details :</b>																				
<b>Expiry Date :</b>	31-07-2020 12:00:00		<b>Type :</b>	Comprehensive																
<b>Product Name :</b>	Access																			
<b>Complain :</b>	ground floor vip lift main entrance door access card reader beeping sound issue																			
<b>Technician Comment :</b>	Vip lift door access check temper beep sound issue resolved but divice under observation 2-3 day Bcz divice hang also then power supply change next time under observation																			
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																			
<b>Remark :</b>	Vip lift door access check temper beep sound issue resolved but divice under observation 2-3 day Bcz divice hang also then power supply change next time under observation																			
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>11-02-2023 10:45:14</td><td>Ravi Rajbhar</td><td>Completed</td><td>Vip lift door access check temper beep sound issue resolved but divice under observation 2-3 day Bcz divice hang also then power supply change next time under observation</td><td></td></tr><tr><td>11-02-2023 10:06:46</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	11-02-2023 10:45:14	Ravi Rajbhar	Completed	Vip lift door access check temper beep sound issue resolved but divice under observation 2-3 day Bcz divice hang also then power supply change next time under observation		11-02-2023 10:06:46	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																
11-02-2023 10:45:14	Ravi Rajbhar	Completed	Vip lift door access check temper beep sound issue resolved but divice under observation 2-3 day Bcz divice hang also then power supply change next time under observation																	
11-02-2023 10:06:46	Ravi Rajbhar	New		-																
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>09-02-2023 11:02:18</td><td>MayurYadav</td><td>VIP lift entrance access card reader issue solve device temper alarm remove</td></tr><tr><td>09-02-2023 10:55:15</td><td></td><td></td></tr></tbody></table>					Date Time	Technician Name	Remark	09-02-2023 11:02:18	MayurYadav	VIP lift entrance access card reader issue solve device temper alarm remove	09-02-2023 10:55:15								
Date Time	Technician Name	Remark																		
09-02-2023 11:02:18	MayurYadav	VIP lift entrance access card reader issue solve device temper alarm remove																		
09-02-2023 10:55:15																				