




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE6444</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9810080819																								
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	26-09-2022 10:52:36																						
<b>Vendor Details :</b>																									
<b>Company Name/Client Name :</b>	Neil J Control	<b>Customer's Mobile :</b>	9810080819	<b>Name :</b>	Dabral Sir																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>																						
<b>Product Name :</b>	CCTV																								
<b>Complain :</b>	1 ip camera off issue 5-6 mtr cat 6 cabling need to do																								
<b>Technician Comment :</b>	cabling allredy done set angel Lawan pathway camera and also use 1 nos ip66 connector working ok and bike entrance camera issue resolved by recogneetion. lo also checked finance camera camera need to changed .																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	cabling allredy done set angel Lawan pathway camera and also use 1 nos ip66 connector working ok and bike entrance camera issue resolved by recogneetion. lo also checked finance camera camera need to changed .																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>26-09-2022 12:36:28</td><td>Atique Salmani</td><td>Completed</td><td>cabling allredy done set angel Lawan pathway camera and also use 1 nos ip66 connector working ok and bike entrance camera issue resolved by recogneetion. lo also checked finance camera camera need to changed .</td><td></td></tr><tr><td>26-09-2022 10:52:58</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>26-09-2022 10:52:37</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	26-09-2022 12:36:28	Atique Salmani	Completed	cabling allredy done set angel Lawan pathway camera and also use 1 nos ip66 connector working ok and bike entrance camera issue resolved by recogneetion. lo also checked finance camera camera need to changed .		26-09-2022 10:52:58	Atique Salmani	New		-	26-09-2022 10:52:37	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
26-09-2022 12:36:28	Atique Salmani	Completed	cabling allredy done set angel Lawan pathway camera and also use 1 nos ip66 connector working ok and bike entrance camera issue resolved by recogneetion. lo also checked finance camera camera need to changed .																						
26-09-2022 10:52:58	Atique Salmani	New		-																					
26-09-2022 10:52:37	Atique Salmani	New		-																					

Previous Complain History :	Date Time	Technician Name	Remark
	19-08-2022 05:06:48	Atique Salmani	One camera ip changed and Camera location swimming pool and ip 11.154.8.104 Port 80 User.admin Pass.admin@123 Angel set working ok.
	15-07-2022 10:56:39	Atique Salmani	camera faulty. 1.Lawan pathway 2.metal post camera plus cable also 3 bike parking camera faulty all fallty cameras hand over to Mahesh sir and L&t gate camera and swimming pool camera issue resolved second swimming pool camera set angel plus cleaning lense and kiitty sue cameras housing missing . and in NVR use desktop hdd so it's being cruppted again again so we suggest for servillence Hdd. instead of desktop hdd.nvr 2 11.154.8.200 NVR is working is properly there is no problem with NVR . problem with hdd which need to be changed .