


Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE6544					
Priority :	Low				
Created By :	Admin - Apurva Vajaria				
Complaint Mob. No. :	9810080819				
Technician Name :	Chandan Yadav		Technician Mobile :	9833262842	
Ticket Type :	Complain	Date & Time :	10-10-2022 12:01:57		
Vendor Details :					
Company Name/Client Name :	Neil J Control	Customer's Mobile :	9810080819	Name :	Dabral Sir
Address :					
Mumbai , , , , Maharashtra					
AMC Details :					
Expiry Date :	01-01-1970 05:30:00		Type :		
Product Name :	CCTV				
Complain :	2-3 IP cameras off issue				
Technician Comment :	5 anlog camera not working and 1 ip camera 2 camera change the BNC and dc and 3 camera dayrek. one ip camera working.one bullate camera new requirements and dome camera.cctv working ok				
Complain Operator :	Desktop - Apurva Vajaria				
Remark :	5 anlog camera not working and 1 ip camera 2 camera change the BNC and dc and 3 camera dayrek. one ip camera working.one bullate camera new requirements and dome camera.cctv working ok				
Status History :	Date Time	Technician Name	Status	Remark	Sign
	10-10-2022 05:47:58	ChandanYadav	Completed	5 anlog camera not working and 1 ip camera 2 camera change the BNC and dc and 3 camera dayrek. one ip camera working.one bullate camera new requirements and dome camera.cctv working ok	
	10-10-2022 12:02:11	ChandanYadav	New		-
	10-10-2022 12:01:57	ChandanYadav	New		-

Previous Complain History :			
	Date Time	Technician Name	Remark
	18-10-2022 02:26:56	Ravi Rajbhar	24 port poe switch also change client side and one camera main porch no video issue resolved but next time need to change cable bcz two pair cable breck and one camera swing pool side angle set 24 port switch handover to client
	26-09-2022 10:52:36	Atique Salmani	cabling allredy done set angel Lawan pathway camera and also use 1 nos ip66 connector working ok and bike entrance camera issue resolved by recocneetion. lo also checked finance camera camera need to changed .