

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE8394																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9810080819																			
Technician Name :	Mayur Yadav		Technician Mobile :	8411951301																
Ticket Type :	Complain	Date & Time :	20-05-2023 05:05:53																	
Vendor Details :																				
Company Name/Client Name :	Neil J Control	Customer's Mobile :	9810080819	Name :	Dabral Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	DVR resolution is not supporting the LED resolution																			
Technician Comment :																				
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	DVR no. 2 HDMI resolution change to 1080P, DVR no. 2 resolution set to 720P DVR view on tv start.																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>27-05-2023 04:24:54</td><td>MayurYadav</td><td>Completed</td><td></td><td>-</td></tr><tr><td>20-05-2023 05:06:07</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	27-05-2023 04:24:54	MayurYadav	Completed		-	20-05-2023 05:06:07	MayurYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																
27-05-2023 04:24:54	MayurYadav	Completed		-																
20-05-2023 05:06:07	MayurYadav	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>08-06-2023 10:44:48</td><td>Atique Salmani</td><td>(1)Sys corridor cameras linse waves issue checked and cahned BNC but same issue also check on vedeo baloon same issue becz cable joint in rj 6 so it's as it's . If need to clear cable need to changed in 1 single piece . (2) 7th floor701 /702 near . new camera changed set angel working ok. (3) engeneering office also camera faulty so which one reommved from 7 floor installed in enenaring office. (4) Reception 2 ip camera shifting plus angel settings done . (5.) Lounge camera also check old camera reinstalled (6) majestic back area corridor reverse phase coming so adaptor not working resolved issue working ok (7) majestic back area camera faulty ohms power ok. (8) apartment 2 camera issue resolved there is SMPS was disconnected so chek n resolve working ok. (9) baloochi back side corridor ip camera cable was remooved from Poe switch so check the cable and connect in Poe switch working ok.</td></tr><tr><td>27-05-2023 10:40:06</td><td>Siddhesh Chavan</td><td></td></tr></tbody></table>					Date Time	Technician Name	Remark	08-06-2023 10:44:48	Atique Salmani	(1)Sys corridor cameras linse waves issue checked and cahned BNC but same issue also check on vedeo baloon same issue becz cable joint in rj 6 so it's as it's . If need to clear cable need to changed in 1 single piece . (2) 7th floor701 /702 near . new camera changed set angel working ok. (3) engeneering office also camera faulty so which one reommved from 7 floor installed in enenaring office. (4) Reception 2 ip camera shifting plus angel settings done . (5.) Lounge camera also check old camera reinstalled (6) majestic back area corridor reverse phase coming so adaptor not working resolved issue working ok (7) majestic back area camera faulty ohms power ok. (8) apartment 2 camera issue resolved there is SMPS was disconnected so chek n resolve working ok. (9) baloochi back side corridor ip camera cable was remooved from Poe switch so check the cable and connect in Poe switch working ok.	27-05-2023 10:40:06	Siddhesh Chavan							
Date Time	Technician Name	Remark																		
08-06-2023 10:44:48	Atique Salmani	(1)Sys corridor cameras linse waves issue checked and cahned BNC but same issue also check on vedeo baloon same issue becz cable joint in rj 6 so it's as it's . If need to clear cable need to changed in 1 single piece . (2) 7th floor701 /702 near . new camera changed set angel working ok. (3) engeneering office also camera faulty so which one reommved from 7 floor installed in enenaring office. (4) Reception 2 ip camera shifting plus angel settings done . (5.) Lounge camera also check old camera reinstalled (6) majestic back area corridor reverse phase coming so adaptor not working resolved issue working ok (7) majestic back area camera faulty ohms power ok. (8) apartment 2 camera issue resolved there is SMPS was disconnected so chek n resolve working ok. (9) baloochi back side corridor ip camera cable was remooved from Poe switch so check the cable and connect in Poe switch working ok.																		
27-05-2023 10:40:06	Siddhesh Chavan																			