







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE3872																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	7738444305																													
Technician Name :	Neeraj Chauhan		Technician Mobile :	8898885764																										
Ticket Type :	Complain	Date & Time :	21-09-2021 12:48:03																											
Vendor Details :																														
Company Name/Client Name :	Rahul International - Mira Road	Customer's Mobile :	7738444305	Name :	Darshan Sir																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
Product Name :	CCTV																													
Complain :	camera issue																													
Technician Comment :	5 dvr ip change and 1 office monitor show camera. 5 dvr IP issues by IT Team.																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	5 dvr ip change and 1 office monitor show camera. 5 dvr IP issues by IT Team.																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>21-09-2021 03:57:07</td><td>Neeraj Chauhan</td><td>Work Pending</td><td>5 dvr ip change and 1 office monitor show camera. 5 dvr IP issues by IT Team.</td><td></td></tr><tr><td>21-09-2021 01:20:17</td><td>Neeraj Chauhan</td><td>Completed</td><td>1 biometric and 1 power adapter and checking purpose send to office.</td><td></td></tr><tr><td>21-09-2021 12:48:16</td><td>Neeraj Chauhan</td><td>New</td><td></td><td>-</td></tr><tr><td>21-09-2021 12:48:03</td><td>Neeraj Chauhan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	21-09-2021 03:57:07	Neeraj Chauhan	Work Pending	5 dvr ip change and 1 office monitor show camera. 5 dvr IP issues by IT Team.		21-09-2021 01:20:17	Neeraj Chauhan	Completed	1 biometric and 1 power adapter and checking purpose send to office.		21-09-2021 12:48:16	Neeraj Chauhan	New		-	21-09-2021 12:48:03	Neeraj Chauhan	New		-
Date Time	Technician Name	Status	Remark	Sign																										
21-09-2021 03:57:07	Neeraj Chauhan	Work Pending	5 dvr ip change and 1 office monitor show camera. 5 dvr IP issues by IT Team.																											
21-09-2021 01:20:17	Neeraj Chauhan	Completed	1 biometric and 1 power adapter and checking purpose send to office.																											
21-09-2021 12:48:16	Neeraj Chauhan	New		-																										
21-09-2021 12:48:03	Neeraj Chauhan	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>31-07-2023 12:50:18</td><td>Atique Salmani</td><td></td></tr><tr><td>26-07-2023 10:15:38</td><td>Sonu Kumar</td><td>4th floor 409 out side camera installed and 6th floor studio room 2 recrimping camera working ok and 1st floor 113 out side 1 video ballon changed and all system chek working ok</td></tr></tbody></table>					Date Time	Technician Name	Remark	31-07-2023 12:50:18	Atique Salmani		26-07-2023 10:15:38	Sonu Kumar	4th floor 409 out side camera installed and 6th floor studio room 2 recrimping camera working ok and 1st floor 113 out side 1 video ballon changed and all system chek working ok																
Date Time	Technician Name	Remark																												
31-07-2023 12:50:18	Atique Salmani																													
26-07-2023 10:15:38	Sonu Kumar	4th floor 409 out side camera installed and 6th floor studio room 2 recrimping camera working ok and 1st floor 113 out side 1 video ballon changed and all system chek working ok																												