

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE5816					
Priority :	Low				
Created By :	Admin - Apurva Vajaria				
Complaint Mob. No. :	7738444305				
Technician Name :	Siddhesh Chavan		Technician Mobile :	8080922985	
Ticket Type :	Complain	Date & Time :	28-06-2022 10:23:22		
Vendor Details :					
Company Name/Client Name :	Rahul International - Mira Road	Customer's Mobile :	7738444305	Name :	Darshan Sir
Address :					
Mumbai , , , , Maharashtra					
AMC Details :					
Expiry Date :	01-01-1970 05:30:00		Type :		
Product Name :	CCTV				
Complain :	cctv survey				
Technician Comment :	8 new dome camera install and one new epabx system install and 10 line contact and working ok and principal sir cabin intercom cable pls check and 1 st floor 1 staircase camera pending and second floor to camera cable not drop and ground floor counselling room cable not found in NVR side				
Complain Operator :	Desktop - Apurva Vajaria				
Remark :	8 new dome camera install and one new epabx system install and 10 line contact and working ok and principal sir cabin intercom cable pls check and 1 st floor 1 staircase camera pending and second floor to camera cable not drop and ground floor counselling room cable not found in NVR side				

Status History :

Date Time	Technician Name	Status	Remark	Sign
28-11-2022 10:51:51	Siddhesh Chavan	New		-
14-10-2022 11:06:37	Siddhesh Chavan	New		-
12-10-2022 11:32:53	Siddhesh Chavan	New		-
13-09-2022 11:15:05	Siddhesh Chavan	New		-
01-09-2022 10:23:53	Siddhesh Chavan	New		-
30-08-2022 10:16:39	Siddhesh Chavan	New		-
27-08-2022 11:10:10	Siddhesh Chavan	New		-
06-08-2022 03:31:22	Siddhesh Chavan	Client Side	8 new dome camera install and one new epabx system install and 10 line contact and working ok and principal sir cabin intercom cable pls check and 1 st floor 1 staircase camera pending and second floor to camera cable not drop and ground floor counselling room cable not found in NVR side	
04-08-2022 10:42:19	Siddhesh Chavan	New		-
11-07-2022 11:20:18	Siddhesh Chavan	New		-
07-07-2022 10:47:37	Siddhesh Chavan	New		-
30-06-2022 10:25:49	Siddhesh Chavan	New		-
29-06-2022 04:57:09	Siddhesh Chavan	In Progress		-
28-06-2022 05:59:02	Siddhesh Chavan	Completed	cctv survey done and 3 Rd floor to 8 floor 2 -3 class room cable not drop and and 2 -3 passage location cable not drop	
28-06-2022 10:23:35	Siddhesh Chavan	New		-
28-06-2022 10:23:22	Siddhesh Chavan	New		-

Previous Complain History :

Date Time	Technician Name	Remark
31-07-2023 12:50:18	Atique Salmani	
26-07-2023 10:15:38	Sonu Kumar	4th floor 409 out side camera installed and 6th floor studio room 2 recrimping camera working ok and 1st floor 113 out side 1 video ballon changed and all system chek working ok