## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

Service Status Details : VE7061										
Priority:	Low									
Created By:	Admin - Apurva Vajaria									
Complaint Mob. No. :	7738444305									
Technician Name :	Siddhesh Chavan		Technician Mobile	8080922985						
Ticket Type:	Complain Date & Time:		10-12-2022 11:36:19							
Vendor Details :										
Company Name/Client Name :	Rahul International - Mira Road	Customer's Mobile :	7738444305	Name :	Darshan Sir					
Address:										
Mumbai , , , , Ma	aharashtra									
AMC Details :			_							
Expiry Date :	01-01-1970 05:30:00		Type:							
<b>Product Name:</b>	CCTV									
Complain:	CCTV VIEWING PROBLEM IN CM SIR OFFICE									
Technician Comment :	1) cm sir cabine cctv view issue resolved 2) dvr side hdmi extender cat 6 cable disconnect re contact cable and issue resolved 3) Darshan sir pc software download and all dvr and NVR viewing done 4) 8 th floor NVR power disconnect and reconnect supply and all camera working ok 5)principal sir pc software install pending 6)fees counter inside camera working ok 7) Darshan sir and Davies sir software training pending									
Complain Operator :	Desktop - Apurva Vajaria									
Remark :	1) cm sir cabine cctv view issue resolved 2) dvr side hdmi extender cat 6 cable disconnect re contact cable and issue resolved 3) Darshan sir pc software download and all dvr and NVR viewing done 4) 8 th floor NVR power disconnect and reconnect supply and all camera working ok 5)principal sir pc software install pending 6)fees counter inside camera working ok 7) Darshan sir and Davies sir software training pending									

Status History :	Date Time	Technician Name	5	Status	Remark	Sign	
	12-12-2022 10:38:05	Siddhesh Chavan	Ne	W		-	
	10-12-2022 01:45:24	Siddhesh Chavan	Wo Per	ork nding	1) cm sir cabine cctv view issue resolved 2) dvr side hdmi extender cat 6 cable disconnect re contact cable and issue resolved 3) Darshan sir pc software download and all dvr and NVR viewing done 4) 8 th floor NVR power disconnect and reconnect supply and all camera working ok 5)principal sir pc software install pending 6)fees counter inside camera working ok 7) Darshan sir and Davies sir software training pending		
	10-12-2022 11:36:31	Siddhesh Chavan	New			-	
Previous Complain History:	Date Time	Technician N	ame	Remark			
	31-07-2023 12:50:1	8 Atique Salmar	ni				
	26-07-2023 10:15:3	8 Sonu Kumar		4th floor 409 out side camera installed and 6th floor studio room 2 recrimping camera working ok and 1st floor 113 out side 1 video ballon changed and all system chek working ok		r 113 out side	