




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE7347																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	7738444305																			
Technician Name :	Sonu Kumar		Technician Mobile :	8454016444																
Ticket Type :	Complain	Date & Time :	12-01-2023 11:28:25																	
Vendor Details :																				
Company Name/Client Name :	Rahul International - Mira Road	Customer's Mobile :	7738444305	Name :	Darshan Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	ground floor backside DVR is not working and the cameras are not seen on screen																			
Technician Comment :	Ground floor back side dvr not working issue resolved and moniter viving issue resolved working ok																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	Ground floor back side dvr not working issue resolved and moniter viving issue resolved working ok																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>12-01-2023 02:45:39</td><td>Sonu Kumar</td><td>Completed</td><td>Ground floor back side dvr not working issue resolved and moniter viving issue resolved working ok</td><td></td></tr><tr><td>12-01-2023 11:29:39</td><td>Sonu Kumar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	12-01-2023 02:45:39	Sonu Kumar	Completed	Ground floor back side dvr not working issue resolved and moniter viving issue resolved working ok		12-01-2023 11:29:39	Sonu Kumar	New		-
Date Time	Technician Name	Status	Remark	Sign																
12-01-2023 02:45:39	Sonu Kumar	Completed	Ground floor back side dvr not working issue resolved and moniter viving issue resolved working ok																	
12-01-2023 11:29:39	Sonu Kumar	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>18-01-2023 11:27:04</td><td>Siddhesh Chavan</td><td>1) 3rd floor lift side dvr ip config and ip chnge and issue resolved and 3 floor staircase side dvr date time ok 2) out 2 camera cable not drop 3) 4 no gate cable not drop at location 4) 5 no gate to NVR side cable issue new cable not drop 5) canteen side DVR to NVR side 2 cable not drop</td></tr><tr><td>13-01-2023 02:30:23</td><td>Sonu Kumar</td><td>Back side dvr not working issue resolved working ok and strong room blackout issue resolved and board room blr issue resolved working ok</td></tr></tbody></table>					Date Time	Technician Name	Remark	18-01-2023 11:27:04	Siddhesh Chavan	1) 3rd floor lift side dvr ip config and ip chnge and issue resolved and 3 floor staircase side dvr date time ok 2) out 2 camera cable not drop 3) 4 no gate cable not drop at location 4) 5 no gate to NVR side cable issue new cable not drop 5) canteen side DVR to NVR side 2 cable not drop	13-01-2023 02:30:23	Sonu Kumar	Back side dvr not working issue resolved working ok and strong room blackout issue resolved and board room blr issue resolved working ok						
Date Time	Technician Name	Remark																		
18-01-2023 11:27:04	Siddhesh Chavan	1) 3rd floor lift side dvr ip config and ip chnge and issue resolved and 3 floor staircase side dvr date time ok 2) out 2 camera cable not drop 3) 4 no gate cable not drop at location 4) 5 no gate to NVR side cable issue new cable not drop 5) canteen side DVR to NVR side 2 cable not drop																		
13-01-2023 02:30:23	Sonu Kumar	Back side dvr not working issue resolved working ok and strong room blackout issue resolved and board room blr issue resolved working ok																		