Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

E: vallabnsecure@yanoo.co.in						
Service Status Det	ails: VE7364					
Priority:	Low					
Created By:	Admin - Apurva Vajaria					
Complaint Mob. No. :	7738444305					
Technician Name :	Sonu Kumar		Technici :	an Mobile 8454016444		
Ticket Type :	Complain	Date & Time :	13-01-20	01-2023 02:30:23		
Vendor Details :			•			
Company Name/Client Name :	Rahul International - Mira Road	Customer's Mobile :	7738444	305	Name :	Darshan Sir
Address:						
Mumbai,,,,Mah	arashtra					
AMC Details :						
Expiry Date :	01-01-1970 05:30:00		Type:	Type:		
Product Name:	CCTV					
Complain :	Strong room camera blackout issue Ground floor DVR backside not any cameras are showing 1-2 cameras blur issue(Conference room)					
Technician Comment :	Back side dvr not working issue resolved working ok and strong room blackout issue resolved and board room blr issue resolved working ok					
Complain Operator :	Desktop - Apurva Vajaria					
Remark:	Back side dvr not working issue resolved working ok and strong room blackout issue resolved and board room blr issue resolved working ok					
Status History:	Date Time	Technician Name	Status	Remark		Sign
	13-01-2023 05:29:17	Sonu Kumar	Completed	Back side dvr not working issue resolved working ok and strong room blackout issue resolved and board room blr issue resolved working ok		d Miles
	13-01-2023 02:30:54	Sonu Kumar	New	-		
Previous Complain	Date Time	Technician Name	Remark			
History:	18-01-2023 11:27:04	Siddhesh Chavan	1) 3rd floor lift side dvr ip config and ip chnge and issue resolved and 3 floor staircase side dvr date time ok 2) out 2 camera cable not drop 3) 4 no gate cable not drop at location 4) 5 no gate to NVR side cable issue new cable not drop 5) canteen side DVR to NVR side 2 cable not drop			
	12-01-2023 11:28:25	Sonu Kumar	Ground floor back side dvr not working issue resolved and moniter viving issue resolved working ok			