Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

E . vanabnisecure@yar							
Service Status De	tails: VE8196						
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	7738444305						
Technician Name :	Sonu Kumar		Technician Me	Technician Mobile 845401644			
Ticket Type :	Complain	Date & Time :	25-04-2023 10:15:21				
Vendor Details :	•		•				
Company Name/Client Name :	Rahul International - Mira Road	Customer's Mobile :	7738444305	Name :	Darshan Sir		
Address :	-						
Mumbai , , , , Ma	harashtra						
AMC Details :							
Expiry Date :	01-01-1970 05:30:00		Type:				
Product Name :	CCTV						
Complain:	2 camera off issue						
Technician Comment :	7 floor 1 camera install working done 6 floor pc online 7 floor camera not working issue resolved.						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	7 floor 1 camera install working done 6 floor pc online 7 floor camera not working issue resolved.						
Status History :	Date Time	Technician Name	Status	Remark	Sign		
	20-06-2023 10:57:19	Sonu Kumar	New		-		
	26-05-2023 10:34:48	Sonu Kumar	New		-		
	22-05-2023 05:04:04	Sonu Kumar	Work Pending	7 floor 1 camera ins working done 6 floo online 7 floor camer not working issue resolved.	rpc () M		
	22-05-2023 11:48:46	Sonu Kumar	New		-		
	05-05-2023 05:21:59	Sonu Kumar	New		-		
	03-05-2023 10:35:19	Sonu Kumar	New		-		
	29-04-2023 10:20:24	Sonu Kumar	New		-		
	28-04-2023 10:38:01	Sonu Kumar	New		-		
	26-04-2023 02:02:58	Sonu Kumar	New		-		
	25-04-2023 10:15:32	Sonu Kumar	New		-		

Previous Complain History :	Date Time 09-08-2023 12:24:24	Technician Name Sonu Kumar	Remark Fees counter all ready camera installed
	09-08-2023 11:10:59	PravinJagade	1. Gate no 3_4_5_ and foot baal and bolly ball area camera offline issue resolved working ok 2. 7th floor boy common room camera faulty collect from reapering. 3.Counseling room no video issue resolve ok 4. 805 angle setting done. 5. Sum camera need for naming 6. Main Reception 4 camera install but 2 camera viewing found and 2 camera not viewing not found