

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE8619																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	7738444305																			
Technician Name :	Kalpesh Subhash Gurav		Technician Mobile :	8879684054																
Ticket Type :	Complain	Date & Time :	21-06-2023 10:05:07																	
Vendor Details :																				
Company Name/Client Name :	Rahul International - Mira Road	Customer's Mobile :	7738444305	Name :	Darshan Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	Intercom																			
Complain :	Intercom issue at security gates and business head cabin																			
Technician Comment :	Anil Sir Cabin Ext. No. 109 OK Security Gate No. 3 Ext. No.117 OK Security Cabin No. 4&5 Cable Not Found																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	Anil Sir Cabin Ext. No. 109 OK Security Gate No. 3 Ext. No.117 OK Security Cabin No. 4&5 Cable Not Found																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>21-06-2023 02:57:39</td><td>Kalpesh SubhashGurav</td><td>Completed</td><td>Anil Sir Cabin Ext. No. 109 OK Security Gate No. 3 Ext. No.117 OK Security Cabin No. 4&5 Cable Not Found</td><td>S. m. Desai</td></tr><tr><td>21-06-2023 10:05:13</td><td>Kalpesh SubhashGurav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	21-06-2023 02:57:39	Kalpesh SubhashGurav	Completed	Anil Sir Cabin Ext. No. 109 OK Security Gate No. 3 Ext. No.117 OK Security Cabin No. 4&5 Cable Not Found	S. m. Desai	21-06-2023 10:05:13	Kalpesh SubhashGurav	New		-
Date Time	Technician Name	Status	Remark	Sign																
21-06-2023 02:57:39	Kalpesh SubhashGurav	Completed	Anil Sir Cabin Ext. No. 109 OK Security Gate No. 3 Ext. No.117 OK Security Cabin No. 4&5 Cable Not Found	S. m. Desai																
21-06-2023 10:05:13	Kalpesh SubhashGurav	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>17-07-2023 11:27:16</td><td>Sonu Kumar</td><td>5th floor studio room 2 and 6th floor lift passage camera off issue resolved working ok</td></tr><tr><td>14-07-2023 03:57:33</td><td>Sonu Kumar</td><td>Ris Mira road 1._ 8th floor class room 808 and terrace lift side camera installed 2._ 7th floor stair case side camera installed 3._ 6th floor lift passage camera installed 4._ 5th floor staircase 2 side camera installed 5._ 3rd floor dvr recording issue resolved and 4 camera angle settings done 6._ 4th floor all camera working ok and 409 out side camera pending camera reapering</td></tr></tbody></table>					Date Time	Technician Name	Remark	17-07-2023 11:27:16	Sonu Kumar	5th floor studio room 2 and 6th floor lift passage camera off issue resolved working ok	14-07-2023 03:57:33	Sonu Kumar	Ris Mira road 1._ 8th floor class room 808 and terrace lift side camera installed 2._ 7th floor stair case side camera installed 3._ 6th floor lift passage camera installed 4._ 5th floor staircase 2 side camera installed 5._ 3rd floor dvr recording issue resolved and 4 camera angle settings done 6._ 4th floor all camera working ok and 409 out side camera pending camera reapering						
Date Time	Technician Name	Remark																		
17-07-2023 11:27:16	Sonu Kumar	5th floor studio room 2 and 6th floor lift passage camera off issue resolved working ok																		
14-07-2023 03:57:33	Sonu Kumar	Ris Mira road 1._ 8th floor class room 808 and terrace lift side camera installed 2._ 7th floor stair case side camera installed 3._ 6th floor lift passage camera installed 4._ 5th floor staircase 2 side camera installed 5._ 3rd floor dvr recording issue resolved and 4 camera angle settings done 6._ 4th floor all camera working ok and 409 out side camera pending camera reapering																		