

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE459																																			
Priority :	Low																																		
Created By :	Admin - Apurva Vajaria																																		
Complaint Mob. No. :	9920234005																																		
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																															
Ticket Type :	Complain	Date & Time :	27-09-2019 11:54:33																																
Vendor Details :																																			
Company Name/Client Name :	Ashford Royale	Customer's Mobile :	9920234005	Name :	Deepak Sir																														
Address :																																			
Mumbai , , , 400078 , Maharashtra																																			
AMC Details :																																			
Expiry Date :	01-01-1970 05:30:00		Type :																																
Product Name :	VDP																																		
Complain :	d1102 issue Continuous bell																																		
Technician Comment :	screen pcb display changed n also door camera pcb changed working ok																																		
Complain Operator :	Desktop - Apurva Vajaria																																		
Remark :	screen pcb display changed n also door camera pcb changed working ok																																		
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>17-10-2019 04:49:45</td><td>Atique Salmani</td><td>Completed</td><td>screen pcb display changed n also door camera pcb changed working ok</td><td></td></tr><tr><td>16-10-2019 11:37:08</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>09-10-2019 01:18:32</td><td>Atique Salmani</td><td>In Progress</td><td>while visit no issue found in vdp client need a multifunction vdp for testing purpose</td><td></td></tr><tr><td>09-10-2019 10:45:08</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>27-09-2019 11:54:34</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	17-10-2019 04:49:45	Atique Salmani	Completed	screen pcb display changed n also door camera pcb changed working ok		16-10-2019 11:37:08	Atique Salmani	New		-	09-10-2019 01:18:32	Atique Salmani	In Progress	while visit no issue found in vdp client need a multifunction vdp for testing purpose		09-10-2019 10:45:08	Atique Salmani	New		-	27-09-2019 11:54:34	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																															
17-10-2019 04:49:45	Atique Salmani	Completed	screen pcb display changed n also door camera pcb changed working ok																																
16-10-2019 11:37:08	Atique Salmani	New		-																															
09-10-2019 01:18:32	Atique Salmani	In Progress	while visit no issue found in vdp client need a multifunction vdp for testing purpose																																
09-10-2019 10:45:08	Atique Salmani	New		-																															
27-09-2019 11:54:34	Atique Salmani	New		-																															
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>31-07-2023 12:52:32</td><td>Ravi Rajbhar</td><td></td></tr><tr><td>31-03-2023 10:37:16</td><td>Ravi Rajbhar</td><td>b wing 202 video door phone out door camera reinstallation done and ok working done and 750 cash collat</td></tr></tbody></table>					Date Time	Technician Name	Remark	31-07-2023 12:52:32	Ravi Rajbhar		31-03-2023 10:37:16	Ravi Rajbhar	b wing 202 video door phone out door camera reinstallation done and ok working done and 750 cash collat																					
Date Time	Technician Name	Remark																																	
31-07-2023 12:52:32	Ravi Rajbhar																																		
31-03-2023 10:37:16	Ravi Rajbhar	b wing 202 video door phone out door camera reinstallation done and ok working done and 750 cash collat																																	