







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE3341																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	9870067773																													
Technician Name :	Siddhesh Chavan		Technician Mobile :	8080922985																										
Ticket Type :	Call Basis	Date & Time :	30-06-2021 10:10:34																											
Vendor Details :																														
Company Name/Client Name :	Scheitel Security Systems	Customer's Mobile :	9870067773	Name :	Dharmil Shah																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
Product Name :	Access																													
Complain :	4 door panel software installation add fingerprint and cards site - dadar																													
Technician Comment :	4 door panel software install and all satting done and panel firmware issue resolved and all door ascces																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	4 door panel software install and all satting done and panel firmware issue resolved and all door ascces																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>30-06-2021 06:35:31</td><td>Siddhesh Chavan</td><td>Completed</td><td>4 door panel software install and all satting done and panel firmware issue resolved and all door ascces</td><td></td></tr><tr><td>30-06-2021 06:35:30</td><td>Siddhesh Chavan</td><td>Completed</td><td>4 door panel software install and all satting done and panel firmware issue resolved and all door ascces</td><td></td></tr><tr><td>30-06-2021 10:10:45</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>30-06-2021 10:10:34</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	30-06-2021 06:35:31	Siddhesh Chavan	Completed	4 door panel software install and all satting done and panel firmware issue resolved and all door ascces		30-06-2021 06:35:30	Siddhesh Chavan	Completed	4 door panel software install and all satting done and panel firmware issue resolved and all door ascces		30-06-2021 10:10:45	Siddhesh Chavan	New		-	30-06-2021 10:10:34	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																										
30-06-2021 06:35:31	Siddhesh Chavan	Completed	4 door panel software install and all satting done and panel firmware issue resolved and all door ascces																											
30-06-2021 06:35:30	Siddhesh Chavan	Completed	4 door panel software install and all satting done and panel firmware issue resolved and all door ascces																											
30-06-2021 10:10:45	Siddhesh Chavan	New		-																										
30-06-2021 10:10:34	Siddhesh Chavan	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>14-08-2021 04:10:21</td><td>Siddhesh Chavan</td><td>Khar adidas intrusion panel inside one cancter loose please resolved permently and panel cancter press and panel issue resolved</td></tr><tr><td>20-07-2021 06:43:21</td><td>MayurYadav</td><td>intrusion zone reconnection and bypass at panel side keep under observation</td></tr></tbody></table>					Date Time	Technician Name	Remark	14-08-2021 04:10:21	Siddhesh Chavan	Khar adidas intrusion panel inside one cancter loose please resolved permently and panel cancter press and panel issue resolved	20-07-2021 06:43:21	MayurYadav	intrusion zone reconnection and bypass at panel side keep under observation																
Date Time	Technician Name	Remark																												
14-08-2021 04:10:21	Siddhesh Chavan	Khar adidas intrusion panel inside one cancter loose please resolved permently and panel cancter press and panel issue resolved																												
20-07-2021 06:43:21	MayurYadav	intrusion zone reconnection and bypass at panel side keep under observation																												