




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE3472																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9870067773																								
Technician Name :	Mayur Yadav		Technician Mobile :	8411951301																					
Ticket Type :	Complain	Date & Time :	20-07-2021 06:43:21																						
Vendor Details :																									
Company Name/Client Name :	Scheitel Security Systems	Customer's Mobile :	9870067773	Name :	Dharmil Shah																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	intrusion																								
Complain :	sensor issue																								
Technician Comment :	intrusion zone reconnection and bypass at panel side keep under observation																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	intrusion zone reconnection and bypass at panel side keep under observation																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>21-07-2021 12:23:23</td><td>MayurYadav</td><td>Completed</td><td>intrusion zone reconnection and bypass at panel side keep under observation</td><td></td></tr><tr><td>20-07-2021 06:43:34</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>20-07-2021 06:43:21</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	21-07-2021 12:23:23	MayurYadav	Completed	intrusion zone reconnection and bypass at panel side keep under observation		20-07-2021 06:43:34	MayurYadav	New		-	20-07-2021 06:43:21	MayurYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																					
21-07-2021 12:23:23	MayurYadav	Completed	intrusion zone reconnection and bypass at panel side keep under observation																						
20-07-2021 06:43:34	MayurYadav	New		-																					
20-07-2021 06:43:21	MayurYadav	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>14-08-2021 04:10:21</td><td>Siddhesh Chavan</td><td>Khar adidas intrusion panel inside one cancter loose please resolved permently and panel cancter press and panel issue resolved</td></tr><tr><td>13-07-2021 10:37:10</td><td>MayurYadav</td><td>pir sensor sensitivity set to low under observation for two days</td></tr></tbody></table>					Date Time	Technician Name	Remark	14-08-2021 04:10:21	Siddhesh Chavan	Khar adidas intrusion panel inside one cancter loose please resolved permently and panel cancter press and panel issue resolved	13-07-2021 10:37:10	MayurYadav	pir sensor sensitivity set to low under observation for two days											
Date Time	Technician Name	Remark																							
14-08-2021 04:10:21	Siddhesh Chavan	Khar adidas intrusion panel inside one cancter loose please resolved permently and panel cancter press and panel issue resolved																							
13-07-2021 10:37:10	MayurYadav	pir sensor sensitivity set to low under observation for two days																							