Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

E: vallabhsecure@yahoo.co.in									
Service Status Det	ails : VE11117								
Priority:	Low								
Created By:	Admin - Apurva Vajaria								
Complaint Mob. No. :	9820536525								
Technician Name:	Atique Salmani			Technicia :	an Mobile 8080922984				
Ticket Type :	AMC visiting Date & Time :			14-03-2024 11:25:09					
Vendor Details :									
Company Name/Client Name :	Vireshwar Heights	C :	'ustomer's Mo	bile	98205365	25	Name :	Dhiru Sir	
Address:									
Mumbai , , , , Mah	arashtra								
AMC Details :									
Expiry Date :	01-01-1970 05:30:00				Type:				
Product Name:	Ppm								
Complain:	Intercom PPM need to do								
Technician Comment :	Intercom ppm done 703 issues resolved and 1004 also check line ok phone issue need to changed .								
Complain Operator :	Desktop - Apurva Vajaria								
Remark:	Intercom ppm done 703 issues resolved and 1004 also check line ok phone issue need to changed .								
Status History:	Date Time		Technician Name		Status	Remark		Sign	
	15-03-2024 11:00:53		Atique Salmani		Completed	issues resolv also check li	om ppm done 703 s resolved and 1004 heck line ok phone need to changed .		
	15-03-2024 10:00:35		Atique Salmani		New	-		-	
Previous Complain History	Date Time	Date Time Technician Name					ark		
	26-03-2024 11:46:21	11:46:21 SD				ru sir home one wifi camera install with configuration done but card not install our side it's not recoding available and cmaera vorking user id - 9820684385 password - admin@123			
	16-03-202 <u>4</u> 02:30:55	Ati	ique Salmani	New memory card installed and formatted recording on in wifi camera and dhiru bhai home cable trace and find out cable is on 12 floor duct also taging on cable and camera end BNC dc changed and set angel working ok of lobby view in dhiru bhai home also checked 1402 intercom comax vdp ringer issue need to changed basic phone client will confirm.					